

RECEIVED

District I
1625 N. French Dr., Hobbs. NM 88240
District II
1301 W. Grand Avenue. Artesia. NM 88210
District III
1000 Rio Brazos Road. Aztec. NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe. NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUN 11 2009
Form C-141
Revised October 10, 2003
HOBBSCOCD
Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action**OPERATOR**☒ Initial Report ☐ Final Report



Name of Company: Targa Midstream Services L P	Contact: Tim Jordan or Ralph England
Address: PO Box 1689 Lovington, NM 88260	Telephone No. (575) 396-3221
Facility Name: Saunders Plant	Facility Type: Gas Processing Plant

Surface Owner: Etcheverry (Middle)	Mineral Owner:	Lease No.
---------------------------------------	----------------	-----------

LOCATION OF RELEASE

Unit Letter A	Section 1	Township 15S	Range 33E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude N33.05005 Longitude W103.56204**NATURE OF RELEASE**

Type of Release: Natural Gas and Produced Liquid	Volume of Release: Approximately 14.15 mcf of raw gas and unknown amount of Produced liquid.	Volume Recovered: 0
Source of Release: Hole in 4" Pipeline with 14 psig of pressure passing about 70mcf of natural gas with containing 2500ppm of H2S. Line has been taken out of service.	Date and Hour of Occurrence: Not sure	Date and Hour of Discovery 05/05/09 Line monitor aircraft discovered leak.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES. Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken. * A 4 inch gathering line had a leak and released gas and any produced liquids that were lying in the line. Line was repaired with clamp. Line has been taken out of service to prevent future contamination. Contaminated soil will be hauled to an approved landfill. Area will be cleaned to meet OCD guidelines. Line monitor aircraft discovered leak.		
Describe Area Affected and Cleanup Action Taken.* Targa will excavate the contaminated area from leak to include runoff. Contaminated soil will be hauled to an approved landfarm.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Don Embrey	Approved by District Supervisor: 	
Title: Training Specialist	Approval Date: 6.11.09	Expiration Date: 9.11.09
E-mail Address: dembrey@targaresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06/09/09 Phone: (432) 688-0546	IRP* 09.6.2201	

* Attach Additional Sheets If Necessary

FGR 0916355498