

District I
162 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ExxonMobil	Contact Toni Collier
Address P.O. Box 4358, Houston, TX 77210	Telephone No. 281-654-1133
Facility Name Greenwood 15	Facility Type Flowline

Surface Owner Charlie Bettis	Mineral Owner	Lease No. N/A
------------------------------	---------------	---------------

LOCATION OF RELEASE

API # 30.025.10136.00.00

Unit Letter M	Section 9	Township 22S	Range 37E	Feet from the 760	North/South Line FSL	Feet from the 660	East/West Line FWL	County Lea
------------------	--------------	-----------------	--------------	----------------------	-------------------------	----------------------	-----------------------	---------------

Latitude 32.24.165 Longitude 103.10.349

NATURE OF RELEASE

Type of Release Oil and Produced Water	Volume of Release 5.28 bbls oil 23.20 bbls water	Volume Recovered 3 bbls oil, 12 bbls water
Source of Release Flowline	Date and Hour of Occurrence	Date and Hour of Discovery 6/20/09 12.00PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mark Whitaker	
By Whom? Shelby Pennington	Date and Hour 6/20/09 5:00PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* No watercourse in area

Describe Cause of Problem and Remedial Action Taken.*

Leak on 2.5" steel flowline due to corrosion. Flowline has been isolated and will be inspected for replacement.

Describe Area Affected and Cleanup Action Taken.*

Area was approx 100 yards east of well #15. Pasture area. A vacuum truck was dispatched immediately to pick up free fluids Remediation of the site has begun. A delineation and remediation plan will be submitted.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kevin M. Dillow</i>	OIL CONSERVATION DIVISION <i>[Signature]</i>	
Printed Name: Kevin M. Dillow	Approved by District ENVIRONMENTAL ENGINEER	
Title: Compliance Supervisor	Approval Date: 7.6.09	Expiration Date: 9.6.09
E-mail Address: Kevin.m.dillow@exxonmobil.com	Conditions of Approval:	
Date: 6/29/09 Phone: 281-654-1557	Attached <input type="checkbox"/> IRP# 09.6.2219	

* Attach Additional Sheets If Necessary

FGRL0918735829

ExxonMobil Production Company
P. O. Box 4358
Houston, Texas 77210-4358

Overnight Mail 1ZV816F70194755408

ExxonMobil
Production

RECEIVED

JUL 02 2009

HOBBSOCD

July 1, 2009

C-141 Form
Blinbry, Drinkard, Tubb Lease
Lea County, New Mexico

State of New Mexico
Oil Conservation Division
District 1
1625 N. French Drive
Hobbs, New Mexico 88240

Dear Sirs:

Please find enclosed the original plus one copy of the C-141 form. The spill of 5.28 barrels of hydrocarbon and 23.2 barrels of produced water occurred on June 20, 2009. Shortly, you shall receive a Delineation plan for this spill for your approval.

If you have any questions or need additional information, please contact Shelby Pennington at (432)596-4211, extension 14.

Sincerely,



Toni L. Collier

tlc
Attachments

CC: State of New Mexico
Oil Conservation Division
1220 South St. Francis Drive
Santa Fe, New Mexico 87505

Bc: Mr. Shelby Pennington
Mr. Doug Parks
Ms. Toni L. Collier
P020A/BDT (Blinbry, Drinkard/Tubb)/Spills