

District I  
1625 N. French Dr , Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr., Santa Fe, NM 87505

RECEIVED

JUL 29 2009

HOBBSOCD

State of New Mexico  
Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

### OPERATOR

X Initial Report ☐ Final Report

Name of Company	Oxy USA WTP	Contact	Dusty Wilson
Address	1017 W. Stanolind Rd	Telephone No.	(575) 397-8247
Facility Name	Lee Stebbins A & B Battery	Facility Type	Storage Facility
Surface Owner	Bull Henson	Mineral Owner	
		Lease No.	

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	5	22s	37e					Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

### NATURE OF RELEASE

Type of Release	Produce Water	Volume of Release	140 bbls	Volume Recovered	130 bbls
Source of Release	Internal corrosion, flow line	Date and Hour of Occurrence	06/21/2009	Date and Hour of Discovery	06/21/2009 @ 10:00 am
Was Immediate Notice Given?	X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jeff Leking		
By Whom?	Dusty Wilson	Date and Hour	06/22/09 @ 8:15 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	n/a		
If a Watercourse was Impacted, Describe Fully.*  N/A					
Describe Cause of Problem and Remedial Action Taken.* Flow line at transfer pump separated causing produce water to spill into battery area. Spill stayed within battery secondary containment walls. Secondary containment is lined with plastic bladder, showing to be intact and in good working condition. Majority of produce water was recovered via vac truck at the time of discovery. Remediation efforts to be determined.					
Describe Area Affected and Cleanup Action Taken.*  Remediate to NMOCD Requirements. Remediation efforts to be determined.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Dusty L. Wilson		Approved by:  District Supervisor:			
Title: HES Specialist		Approval Date: 08/17/09		Expiration Date: 10/16/09	
E-mail Address: dusty_wilson@oxy.com		Conditions of Approval: submit FINAL BY 10/16/09.		Attached <input type="checkbox"/>	
Date: 06/23/2009		Phone: (575) 397-8210		IRP-09-8-2262	

- Attach Additional Sheets If Necessary

FGRL09 22928346