<u>District I</u> . 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV

## State of New Mexico **Energy Minerals and Natural Resources**

FEB -6 2009

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Form C-141

Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

30-015-27775

PMUB0927340555727

1220 S. St. Francis Dr., Santa Fe, NM 87505

## **Release Notification and Corrective Action**

MUB-0929	23 40/09	7			OPERATOR				Initial Report	Final Report	
Name of Company Yates Petroleum Corporation						Contact Mike Stubblefield					
Address 105 South 4 <sup>th</sup> Street, Artesia, N.M. 88210						Telephone No. 505-7484500 505-513-1712					
Facility Name Creek AL Federal #12 30-015-27775						Facility Type Oil Well					
Surface Owner B.L.M. Mineral Owner						B.L.M. Lease No.					
				LOC	ATIO	N OF REI	LEASE				
									Vest Line	County	
E	25	18s	30e	1405'	FNL		330'	FWL		Eddy	
	}										
	J	.1		Latitude _	Lon	gitude				<u> </u>	-
				NA'	TURE	OF RELI	EASE				
Type of Relea	se Hydroca	rbon & Produc							Recovered		
					20 bbls Hydrocarbon			10 bbls Hydrocarbon			
Source of Rel	ease Flow 1	ne leak			18 bbls PW Date and Hour of Occurrence			5 bbls Produced water Date and Hour of Discovery			
Source of Release Flow line leak						1/29/2009 9:30am same					
Was Immediate Notice Given?  Yes X No Not Required						If YES, To Whom? NMOCD/Mike Bratcher					
By Whom? A	Aike Stubble		<del></del> _	Date and Hour 1/29/2009 10:55am							
By Whom? Mike Stubblefield Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.					
			lo								
If a Watercou	rse was Imp	acted, Describ	e Fully.*					<u> </u>			
		<u></u>									<u></u> ,
Describe Cause of Problem and Remedial Action Taken.*											
The flow line ruptured, the well was shut-in and a vacuum truck was called to the location.  The flow line was repaired. Free standing fluids were recovered.											
The flow line was repaired. I fee standing fluids were recovered.											
		nd Cleanup Ac			_						
										ial supply pit locate es. The visibly imp	
										er set on the location	
will be taken t	for analytica	al from the exc	avated area	a on location and t	he stock	piled soils. The	soil samples taker			to a second party L	
				od 8015M & B-T				& D TI	V to be un	der the RRAL for th	a sita A Emal
				m the excavated ar ng closure for the				& D-11	ca to be un	der the KKAL for th	ie site, A finai
Depth to grou	nd water ->	50', Wellhead	d protection	n area - > 1000', D	Distance t	to surface wate	r body -> 1000'				
										NMOCD rules and	
										ndanger public heal y should their opera	
failed to adequ	uately inves	tigate and rem	ediate cont	amination that pos	se a threa	at to ground wa	iter, surface water,	human l	health or th	e environment. In a	ddition,
NMOCD acce	eptance of a	C-141 report of	does not re	lieve the operator of	of respon	sibility for con				or local laws and/o	r regulations.
	_						OIL CON	SERV	ATION	DIVISION	
Signature: mais Cellfill						Approved by District Supervisor:					
Title. Environ	mental Reg	ulatory Agent			Approval Date: Expiration Date:						
F-mail Adda	ee mikaa	lmenm ee-			Conditions of Approval:						
E-mail Addre	ss: mikes@;	ypcnm.com				$\sim$				Attached	
Date: 2/6/2			748-4500		REMEDIATION Completed						
Attach Addit	ional Shee	ts If Necessar	ry				,			RD-24	<u>'</u>
Attach Additional Sheets If Necessary  AND 09273 40 555											Γ