

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
SEP 02 2009
HOBBSD

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company OXY USA	Contact Kelton Beaird
Address 1502 W. Commerce	Telephone No. (O) 575-628-4121 C) 575-390-1903
Facility Name State CL Lease	Facility Type Tank Battery

Surface Owner State	Mineral Owner	Lease No.
---------------------	---------------	-----------

LOCATION OF RELEASE

API# 30.025.01574.00.00

Unit Letter B	Section 2	Township 18S	Range 33E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 20 bbls.	Volume Recovered 10bbls.
Source of Release Tank	Date and Hour of Occurrence	Date and Hour of Discovery 8-28-09 @ 10:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson (NMOCD)-left message	
By Whom? Kelton Beaird (HES)	Date and Hour See above	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

WATER 9' 12 5'



Describe Cause of Problem and Remedial Action Taken *

The water-transfer pump failed causing the tank to overflow produced water out of the tank A vac-truck was called to pick up all remaining fluid

Describe Area Affected and Cleanup Action Taken *

Area affected was inside of the containment area. Delineation will be done per NMOCD standards. A work plan will be submitted to the NMOCD for approval.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Kelton Beaird	ENV. ENGINEER: Approved by District Supervisor: 	
Title: HES Specialist	Approval Date: 09/03/09	Expiration Date: 11/03/09
E-mail Address: kelton_beaird@oxy.com	Conditions of Approval: SUBMIT FINAL C-141 BY _____	Attached <input type="checkbox"/>
Date: 8-28-09		IRP-09-10-2290

* Attach Additional Sheets If Necessary

FGRL 0927539292