

District I
1625 N French Dr, Hobbs, NM 88241
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

RECEIVED

SEP 14 2009

HOBBSOCD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	BTA Oil Producers LLC	Contact	Skip Baca
Address	104 S Pecos, Midland, TX 79701	Telephone No.	432-682-3753
Facility Name	Gem, 8705 JV-P Battery	Facility Type	Tank Battery
Surface Owner	State (Ken Smith, Grazing)	Mineral Owner	State
		Lease No.	V-2199

LOCATION OF RELEASE

Unit Letter	C	Section	2	Township	20S	Range	33E	Feet from the	660	North/South Line	North	Feet from the	2310	East/West Line	West	County	Lea
-------------	---	---------	---	----------	-----	-------	-----	---------------	-----	------------------	-------	---------------	------	----------------	------	--------	-----

Latitude _____ Longitude _____

ASSOCD WELL GEM 8705 JV-P
#002
API # 30.025.30468.00.00

NATURE OF RELEASE

Type of Release	Minor	Volume of Release	30 bbls	Volume Recovered	25 bbls
Source of Release	Broken Valve	Date and Hour of Occurrence	10:30 a.m. 09/10/2009	Date and Hour of Discovery	10:30 a.m. 09/10/2009
Was Immediate Notice Given?	Did not have details <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Larry Johnson, voice msg, Hobbs District office		
By Whom?	Pam Inskeep	Date and Hour	7:45 a.m. 09/11/2009		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*



Broken valve on circulating pump. Turned off pump Replaced valve
Vacuum truck recovered 25 bbls of oil, returned to tank.

WATER @ 105'

Describe Area Affected and Cleanup Action Taken.*

Affected area is inside dike. Will remove affected soil and dispose of at Leeland. Will replace with clean soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Pam Inskeep	Approved by: ENV ENGINEER:  District Supervisor	
Title: Regulatory Administrator	Approval Date: 10/08/09	Expiration Date: 12/08/09
E-mail Address: pinskeep@btaoil.com	Conditions of Approval: CONFIRMATION SAMPLING REQUIRED. DELINEATE TO CLEAN + 1 SAMPLE BEYOND	
Date: 09/11/2009 Phone: 432-682-3753	Attached <input type="checkbox"/> IRP-09-10-2293	

* Attach Additional Sheets If Necessary

CLEAN. SUBMIT FINAL C-141
BY 12/08/09.

PGRL 09 28147643