RECEIVED

District I 1625 N. French Dr., Hobbs, NM 88240

State of New Mexico

Form C-141 Revised October 10, 2003

District II
1301 W Grand Avenue, Artesia. NM 8824EP 2 8 20 Finergy Minerals and Natural Resources

District III
1000 Rio Brazos Road, Aztec, NM 87HOBBSOCD District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back side of form

Release Notification and Corrective Action										
OPERATOR X Initial Report Final Report										
Name of Co		Kerns Pet			Contact	Kerry Johns				
Address		VE Loop 41			elephone No. 210-829-7881 acility Type steel water line					
Surface Owner Doom Ranches, Inc. Mineral Owner Fee (16 owners) Lease No. N/A										
LOCATION OF RELEASE										
Unit Letter	Section	Township	Range	Feet from the	North/S	South Line	Feet from the	East/West Line	County	
М	22	24S	37E	1315	So	outh	1315	West	Lea	
Latitude						Longitud	e		WELL KNIGHTOLO (#10)	
AP(#30.025.20351.00.00										
Type of Release Salt water Volume of Release < 25 bbl Volume Recovered none										
							Date and Hour of Occurrency/21/09 Date and Hour of Discovery 9/22/09			
Was Immediate Notice Given?    Yes   No   Not Required   If YES, To Whom?										
							Date and Hour			
By Whom? Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.				
☐ Yes 💢 No										
If a Watercourse was Impacted, Describe Fully.*										
Describe Cause of Problem and Remedial Action Taken.* Old steel water disposed line pine that runs on the curfoce of the Knight										
Old steel water disposal line pipe that runs on the surface of the knight										
property has reached the end of its useful life and is now leaking. We have scheduled the installation of new poly										
pipe to replace the steel line. We expect the poly line to be installed within a week or so.										
Describe Area Affected and Cleanup Action Taken.* The affected area is open range land near the Knight 10 wellsite. There are										
no residences or other culture in proximity to the spot of the leak. The water has evaporated. No clean-up action										
has been taken.										
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and										
regulations a	ll operators	are required t	o report a	nd/or file certain i	clease no	otifications a	nd perform correc	ctive actions for rel	cases which may endanger	
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability										
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other										
federal, state, or local laws and/or regulations.										
1010						OIL CONSERVATION DIVISION				
Signature: Jung Johnston						ENVIRONMENTAL ENGINEER;				
Printed Name: Kerry Johnston						Approved by District Supervisor: SCRED AD ON 2012				
							_ 1 1	100	1-110	
Title: Vice President						Approval Da	c: 09/29/	A   Expiration	Date: 11/30/09	
E-mail Address: kjohnston@kernspetro.com							Approval: DEZ	INFLATE 10	- Attached	
Data: C/O					١,	CLEAN	HANDR	FIMEDIATE	1RP-09-10-2303	
Attach Additional Sheets If Necessary  NMOCD LIMITS. GW 15									•	

FGRL0928747134

SHALLOW AT THIS LOCATION SO IT IS ESPECIALLY IMPORTANT TO SAMPLE AND REMEDIATE IP NECESSARY.