Holdes

<u>District I</u>
1625 N. French Dr , Hobbs, NM 88240
<u>District II</u>
1301 W. Grand Avenue, Artesia, NM 88210
<u>District III</u>
1000 Rio Brazos Road, Aztec, NM 87410
<u>District IV</u>

RECEIVED

State of New Mexico
Energy Minerals and Natural Resources

OCT 0 2 2009

Form C-141 Revised October 10, 2003

RP-09-11-2316

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505 HOBBSOCD Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

O S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505 Santa Fe, NM 87505					side of form			
								
Release Noti	ification	n and Co	orrective A	ction				
		OPERA	TOR	X Init	ial Report	Final	l Repor	
Name of Company Oxy USA WTP		Contact D	ısty Wilson					
Address 1017 W. Stanolind Rd		Telephone 1	No. (575) 397-	8247				
Facility Name MLMU North Injection Line		Facility Typ	e Produce Wat	er Injection				
Surface Owner Kelly Meyers Miner	al Owner (r Oxy, BLM Lease No.						
Surface Owner Reny Weyers 14mor	ui o wher c	ony, DENT	~<	ENERY MINI	1-4133			
		N OF RE	LEASE 30	.025, NO		<i>30</i>		
Unit Letter Section Township Range Feet from the	ne North	South Line	Feet from the	East/West Line	County			
D 5 24s 37e					Lea			
				761	11' 44.8	т. и		
32°15' 8.676 Latitude 32.	.25241	_ Longitud	le 103, 195	<u>19</u> 103°	"11" 44,8	44		
N	ATURE	OF REL	EASE					
Type of Release Oil and Produce Water			Release 5 bo-35	bw Volume	Recovered r	one -		
Source of Release Trunk Line Rupture			Iour of Occurrence		Date and Hour of Discovery 08/19/2009			
Was Immediate Notice Given?			08/19/2009 08/19/2009 If YES, To Whom?					
X Yes \square No \square Not	Jeff Leking							
By Whom? Dusty Wilson/via email	Date and Hour 8/24/2009							
Was a Watercourse Reached?			If YES, Volume Impacting the Watercourse.					
☐ Yes X No		n/a						
If a Watercourse was Impacted, Describe Fully.*		•						
N/A								
IV/A					V			
				WATER(3) 92			
Describe Cause of Problem and Remedial Action Taken.*								
Trunk line ruptured due to corrosion. Remediation efforts con	itinue							
Trank time ruptured due to corrosion. Remediation eriorts con	amuc.							
Describe Area Affected and Cleanup Action Taken.*								
Remediate to NMOCD Requirements.								
Therefore and for the table information aircon above is true and a	ammlata ta tl	a boot of man	len avuladas and v	d anatan d th at	munant to NIM	0CDl	1	
I hereby certify that the information given above is true and coregulations all operators are required to report and/or file certain								
public health or the environment. The acceptance of a C-141								
should their operations have failed to adequately investigate a								
or the environment. In addition, NMOCD acceptance of a C-	141 report d	oes not reliev	e the operator of	responsibility for	compliance v	nth any other		
federal, state, or local laws and/or regulations.	$\frac{1}{2}$		OIL COM	CEDVATION	DIVICIO	N.T.		
			OIL CON.	SERVATION	DIVISIC	<u>IN</u>		
Signature:		;	ENV. ENGINEER	•				
Didate Dal Wi			Approved by District Supervisor: Texporer Laking					
Printed Name Dusty L. Wilson				rackrant	Diversor 6			
Title: HES Specialist		Approval Da	e: 10/05/09	Expiration	Date: 12/6	7/69		
E mail Address dustra miles @		Comdistin						
E-mail Address: dusty_wilson@oxy.com	SUBMIT FINAL C-14 BY 126769. Attached Attached							

• Attach Additional Sheets If Necessary

Phone: (575) 397-8210

Date: 09/15/2009