

1R - 427-62

REPORTS

DATE:

12-15-09



TETRA TECH

RECEIVED OGD

2009 DEC 17 A 11:28

CERTIFIED MAIL
RETURN RECEIPT NO. 7006 0100 0001 2434 0053

December 15, 2009

Mr. Ed Hansen
New Mexico Energy, Minerals, & Natural Resources Dept.
Oil Conservation Division, Environmental Bureau
1220 S. St. Francis Drive
Santa Fe, New Mexico 87505

Re: Monitor Well Plugging Report, Rice Operating Company, Eunice Monument Eumont (EME) Saltwater Disposal System (SWD) A-2 Release, Unit A, Section 2, T-20-S, R-36-E, Lea County, New Mexico, NMOCD CASE #1R0427-62

Mr. Hansen:

Tetra Tech Inc. (Tetra Tech) submits the following Monitor Well Plugging Report for the Rice Operating Company (ROC) A-2 site located in the Eunice Monument Eumont (EME) Saltwater Disposal System (SWD). ROC is the service provider (agent) for the EME SWD System and has no ownership of any portion of the pipeline, well or facility. The EME SWD system is owned by a consortium of oil producers, System Parties, who provide all operating capital on a percentage ownership/usage basis.

Following approval of the termination of this site by the NMOCD on September 16, 2009, Rice Operating Company (ROC) contacted Harrison & Cooper, Inc. to plug the three (3) monitor wells at this site. As shown on the enclosed plugging reports, these monitor wells were plugged on November 2, 2009. Prior to plugging, the casing was pulled from the wellbore and the wells were plugged using a cement grout with 3% bentonite from 3' - 53', and cement from 0-3'. Copies of the plugging reports and photographs are enclosed.

Tetra Tech

1910 North Big Spring, Midland, TX 79705

Tel 432.682.4559 Fax 432.682.3946 www.tetrattech.com



TETRA TECH

ROC acknowledges that they have met the requirements of 19.15.29 NMAC, the NMOCD terminated the remediation plan (1R0427-62) in accordance with 19.15.29 NMAC and no further actions are warranted. If you require any additional information or have any questions or comments, please call at (432) 682-4559 or Hack Conder at (575) 393-9174.

Respectfully submitted,
TETRA TECH

Tim Reed, P.G.
Sr. Project Manager

cc: ROC
Enclosures: Plugging Reports, Photos

APPENDIX A

HARRISON & COOPER, INC.

Drilling & Pump Professionals

7414 85th Street, Lubbock, Texas 79424-4951

P.O. Box 96, Wolfforth, Texas 79382-0096

Ph: (806) 866-4026

Fax: (806) 866-4044

harrisoncooper-drilling.com

Plugging Report

Client	Rice Operating
Contractor	Harrison & Cooper
Date Completed	11/2/2009
Site	EME A-2 Leak
Well ID	MW-1
Casing Diameter	2"
Well Depth	53'
Casing Material	PVC
Plugging Material	Portland/Bentonite Slurry
Slurry Interval	3'-53'
Cement Interval	0'-3'

Copies: File

Email (Lara Weinheimer)

Mail (Rice-Hobbs)

Regulated by: Texas Dept. of Licensing & Regulation, Water Well Division, P.O. Box 12157, Austin, TX 78711, (800) 803-9202

HARRISON & COOPER, INC.

Drilling & Pump Professionals

7414 85th Street, Lubbock, Texas 79424-4951

P.O. Box 96, Wolfforth, Texas 79382-0096

Ph: (806) 866-4026

Fax: (806) 866-4044

harrisoncooper-drilling.com

Plugging Report

Client	Rice Operating
Contractor	Harrison & Cooper
Date Completed	11/2/2009
Site	EME A-2 Leak
Well ID	MW-2
Casing Diameter	2"
Well Depth	53'
Casing Material	PVC
Plugging Material	Portland/Bentonite Slurry
Slurry Interval	3'-53'
Cement Interval	0'-3'

Copies: File

Email (Lara Weinheimer)

Mail (Rice-Hobbs)

Regulated by: Texas Dept. of Licensing & Regulation, Water Well Division, P.O. Box 12157, Austin, TX 78711, (800) 803-9202

HARRISON & COOPER, INC.

Drilling & Pump Professionals

7414 85th Street, Lubbock, Texas 79424-4951

P.O. Box 96, Wolfforth, Texas 79382-0096

Ph: (806) 866-4026

Fax: (806) 866-4044

harrisoncooper-drilling.com

Plugging Report

Client	Rice Operating
Contractor	Harrison & Cooper
Date Completed	11/2/2009
Site	EME A-2 Leak
Well ID	MW-3
Casing Diameter	2"
Well Depth	53'
Casing Material	PVC
Plugging Material	Portland/Bentonite Slurry
Slurry Interval	3'-53'
Cement Interval	0'-3'


Copies: File

Email (Lara Weinheimer)

Mail (Rice-Hobbs)

Regulated by: Texas Dept. of Licensing & Regulation, Water Well Division, P.O. Box 12157, Austin, TX 78711, (800) 803-9202

PHOTOGRAPHS



Remove casings from wells



Plugging wells with a cement bentonite slurry



Hole prior to the 3 ft cement cap



Completed plug and abandon