District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV

State of New Mexico
Engrey Minerals and Natural Resources

JAN 06

Conservation Division

Submit 2 Copies to appropriate District Office in accordance

with Rule 116 on back side of form

Form\C-141 Revised October 10, 2003

JAN US Conservation Division
1000 Rto Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

JAN US Conservation Division
1220 South St. Francis Dr.

Release Notification and Corrective Action											
		•				OPERAT	ΓOR	X	Initial	Report  Final Report	
Name of Company Fasken Oil and Ranch, Ltd.   Contact Jimmy Carlile											
Address 303 W. Wall, Ste. 51800; Midland, TX Telephone No. 432-687-1777											
Facility Name Denton SWD Main Battery Facility Type SWD Emergency Pit											
Surface Owner Darr Angel1 Mineral Owner							Fee Lease No.				
LOCATION OF RELEASE API # 30.025.05309.00.00											
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/West L		Countý	
D	13	15S	37E							Lea	
	L		La	titude		Longitud	e			, , , , , , , , , , , , , , , , , , ,	
NATURE OF RELEASE											
Type of Release Salt Water Volume of Release 680 Volume Recovered 640											
Source of Release Emergency Pit Overflow							Date and Hour of Occurrence Date and Hour of Discovery				
Was Immediate Notice Given?						If YES, To	Whom? 1-2-			1-3-10	
X Yes ☐ No ☐ Not Required						5.50 pm 10.00 am					
By Whom? Jimmy Carlile Was a Watercourse Reached?						Date and Hour 1-4-10 8:47 am Geoff Leking, voicemail If YES, Volume Impacting the Watercourse.					
Yes X No						N/A					
If a Watercourse was Impacted, Describe Fully.*											
N/A											
							WATERO 52				
Describe Cause of Problem and Remedial Action Taken.* Injection pump went down on low suction pressure. Alarms failed due to blown fuse in											
Alltel callout board and Leaco cellular phone weak signal. Re-set pump. Replaced phone											
board and cellular phone.											
Describe Area Affected and Cleanup Action Taken.*											
115' X 200' southoof pit and 70' X 100' east of pit.											
115 A 200 Southwar hat and 70 A 100 East of pit.											
										ant to NMOCD rules and	
										ses which may endanger	
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health											
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
rederal, state,	or local lay	vs and/or regu	mations.				OIL CONS	SERVATI	ON F	DIVISION	
Si sa Kun China							OIL COILE	DEIC VILLE	OITE	277151614	
Signature: Approved by District Supervisor:											
Printed Name	. Jimr	ny Carli	le		<i>F</i>	Approved by	Ustriet Supervise	Theore	reer	Lokma	
Title: Regu	latory	Affairs	Coord	inator	A	Approval Dat	e: 01/08/10	Expira	tion D	ate:03 08 10	
E-mail Address: jimmyc@for1.com Conditions of Approval: DEUNERTEVO											
Date: 1-4-			Phone	432-687-1		LEAN +	"SUBMIT F	MB5 C-141	BY	Attached L	