

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

DEC 31 2009
HOBBSOC

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

X Initial Report ☐ Final Report

Name of Company	Oxy USA WTP	Contact	Dusty Wilson
Address	1017 W. Stanolind Rd	Telephone No.	(575) 397-8247
Facility Name	State 33 # 2 Battery	Facility Type	Storage
Surface Owner	State of NM	Mineral Owner	Shared
		Lease No.	NM-51673

LOCATION OF RELEASE API# 30.025.34144.00.00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	33	21s	35e					Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produce Water	Volume of Release	92 bbls	Volume Recovered	90 bbls
Source of Release	Tank Over flow due to power failure	Date and Hour of Occurrence	10/22/09	Date and Hour of Discovery	Same
Was Immediate Notice Given?	X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jeff Leking		
By Whom?	Dusty Wilson	Date and Hour	10/23/09 0800 hrs		
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	n/a		

If a Watercourse was Impacted, Describe Fully.*

N/A



Describe Cause of Problem and Remedial Action Taken.*

Tank overflowed due to power failure at site. All fluids were contained inside the firewalls at the battery site Remediation efforts will be ongoing.

Describe Area Affected and Cleanup Action Taken.*

Remediate to NMOCD Requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Dusty L. Wilson	ENV ENGINEER: Approved by District Supervisor: 	
Title: HES Specialist	Approval Date: 01/08/10	Expiration Date: 03/08/10
E-mail Address: dusty_wilson@oxy.com	Conditions of Approval: DELINEATE TO CLEAN + 1. SUBMIT FINAL C-141 BY	Attached <input type="checkbox"/> IRP-10.1.2389
Date: 12/22/2009	Phone: (575) 397-8210	

- Attach Additional Sheets If Necessary

FCRL 1000855868