

District I  
1625 N. French Dr , Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St Francis Dr , Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JAN 20 2010

HOBBSD

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report XX Final Report

Name of Company Oxy USA WTP	Contact Dusty Wilson	
Address 1017 W. Stanolind Rd	Telephone No. (575) 397-8247	
Facility Name E C Hill D # 1	Facility Type Well site	
Surface Owner D K Boyd	Mineral Owner Oxy	Lease No. 64118

LOCATION OF RELEASE

APL # 30-025-10947-00-00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	34	23s	37e					Lea

Latitude N32°15'44.9" Longitude W103°08'35.8"

NATURE OF RELEASE

Type of Release Produce Water	Volume of Release 60 bbls	Volume Recovered 20 bbls
Source of Release Flow Line	Date and Hour of Occurrence 07/07/2009 10.00 am	Date and Hour of Discovery Same
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Leking	
By Whom? Dusty Wilson	Date and Hour 07/13/2009 2:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse n/a	

If a Watercourse was Impacted, Describe Fully.\*

N/A



Describe Cause of Problem and Remedial Action Taken.\*

Internal corrosion of flow line. Vac truck deployed and recovered 20 bbls produce water. Remediation efforts complete. The following work plan was agreed upon by NMOCD Personnel according to provided analytical data of this area. A five foot excavation of the affected area was performed and all removed soils were disposed of at an approved disposal site A 20 mil. Liner was placed over the affected area and it was backfilled with clean like soils and closed.

Describe Area Affected and Cleanup Action Taken.\*

Remediated to NMOCD Requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Dusty L. Wilson	Approved by District Supervisor: 	
Title: HES Specialist	Approval Date: 01/29/10	Expiration Date: —
E-mail Address: dusty_wilson@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 01/10/2010 Phone: (575) 397-8210		RP-09-8-2261

- Attach Additional Sheets If Necessary