

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RP. 2456

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company <u>Smith + Marcus</u>	Contact <u>Mike Dennis</u>	
Address <u>Box 863 Kismet Tx</u>	Telephone No. <u>432-940-1890</u>	
Facility Name <u>Knight #14</u>	Facility Type <u>Producing well</u>	
Surface Owner <u>Doom</u>	Mineral Owner	Lease No.

LOCATION OF RELEASE

API# 30-025-27490-00-00

Unit Letter <u>P</u>	Section <u>22</u>	Township <u>24</u>	Range <u>37</u>	Feet from the	North/South Line	Feet from the	East/West Line	County <u>hew</u>
-------------------------	----------------------	-----------------------	--------------------	---------------	------------------	---------------	----------------	----------------------

Latitude 32 11 57 Longitude 103 09 40

NATURE OF RELEASE

Type of Release <u>Oil + water</u>	Volume of Release <u>3644</u>	Volume Recovered <u>0</u>
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? <u>2/5/10</u> <u>Geoffrey Laking</u>	
By Whom? <u>D. Mucedita</u>	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Repaired flow line / stabilized area, began hauling contamination

Describe Area Affected and Cleanup Action Taken.*

area 100x150 south of well.
Excavated contaminated soil, hauled to Doom Lf. sampled area OGD
approved backfilling. Area was backfilled & leveled.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Mike Dennis</u>		OIL CONSERVATION DIVISION	
Printed Name: <u>Mike Dennis</u>		ENV. ENGINEER: Approved by District Supervisor: <u>Geoffrey Laking</u>	
Title: <u>Production Sept.</u>		Approval Date: <u>03/18/10</u>	Expiration Date: <u>-</u>
E-mail Address:		Conditions of Approval:	Attached <input type="checkbox"/>
Date: <u>3/1/2010</u>	Phone: <u>432-940-1890</u>	IRP-10-3-2456	

* Attach Additional Sheets If Necessary

Submit to Admin Permit

FGRL1007742241

SMITH & MARRS
KNIGHT #14
Unit P, Section 22, Tws. 24 S., Rng. 37 E.

FINAL CLOSURE REPORT
RP 2419

RECEIVED

MAR 03 2010

HOBBSOCD

Prepared By
Eddie Seay Consulting
March 2010

March 1, 2010

NMOCD Environmental
ATTN: Geoffrey Leking
1625 N. French Drive
Hobbs, NM 88240

RE: Smith & Marrs
Knight #14 Spill
RP 2419

Mr. Leking:


Smith and Marrs has completed the remediation of the Knight #14 spill. All contaminated soil, 1752 cu. yds. was hauled to Doom Landfarm for disposal. After excavation, the area was sampled and approved by you for backfilling.

The area has been backfilled and leveled using soil from Doom Ranch.

Find enclosed analytical, photos and final C-141.

If you have any questions, please call.

Sincerely,

A handwritten signature in black ink, appearing to read "Eddie W. Seay", with a long, sweeping underline that extends to the right.

Eddie W. Seay, Agent
Eddie Seay Consulting
601 W. Illinois
Hobbs, NM 88242
(575)392-2236

cc: Smith & Marrs

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company <u>Smith + Moore</u>	Contact <u>Mike Dennis</u>	
Address <u>Box 863 Knight Tx</u>	Telephone No. <u>432. 940. 1890</u>	
Facility Name <u>Knight # 14</u>	Facility Type <u>Prod. well</u>	
Surface Owner <u>Doom</u>	Mineral Owner	Lease No.

LOCATION OF RELEASE

API # 30-025-27490-00-00

Unit Letter <u>P</u>	Section <u>22</u>	Township <u>24</u>	Range <u>37</u>	Feet from the	North/South Line	Feet from the	East/West Line	County <u>hea</u>
----------------------	-------------------	--------------------	-----------------	---------------	------------------	---------------	----------------	-------------------

Latitude 32 11 57 Longitude 103 09 40

NATURE OF RELEASE

Type of Release <u>Production Fluids</u>	Volume of Release <u>364 6/5</u>	Volume Recovered <u>0</u>
Source of Release <u>Flow line leak</u>	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? <u>2/5/10</u> <u>Geoffrey Lohing</u>	
By Whom? <u>D. Munday</u>	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

RECEIVED

If a Watercourse was Impacted, Describe Fully.*

FEB 7 7 2010

HOBBSOCD

WATER @ 65'

Describe Cause of Problem and Remedial Action Taken.*

Hole in poly flow line. Repair flow line. stabilize 39 area.

Describe Area Affected and Cleanup Action Taken.*

Began excavating area affected. / 100x150 south of well.
will file final 141 & analytical when finished.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Eddie Seay</u>	OIL CONSERVATION DIVISION	
Printed Name: <u>Eddie Seay</u>	ENV. ENGINEER: Approved by District Supervisor: <u>Geoffrey Lohing</u>	
Title: <u>Agent</u>	Approval Date: <u>02/11/10</u>	Expiration Date: <u>04/12/10</u>
E-mail Address: <u>seay04@lema.net</u>	Conditions of Approval: <u>SUBMIT FINAL C-141 BY 04/12/10</u>	Attached <input type="checkbox"/>
Date: <u>2/9/10</u>	Phone: <u>392-2236</u>	<u>10P-10.3-2456</u>

* Attach Additional Sheets If Necessary



KEANS PETROLEUM, INC.
KNIGHT #014
UNIT P, SEC. 22-T24S-R37E
1315' FSL & 660' FEL
LEA COUNTY, NEW MEXICO
API #30-025-27490

