

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report



Name of Company: Targa Midstream Services L P	Contact: James Lingnau 575.394.2534, Chuck Tolsma 575.631.6026	
Address: PO Box 1909 Eunice, NM 88231	Telephone No. (575) 394-2534	
Facility Name: Eunice Gas Plant	Facility Type: Natural Gas Processing	
Surface Owner: Deck Estate	Mineral Owner:	Lease No. 30-025-21497

LOCATION OF RELEASE

Unit Letter	Section 22	Township 21S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.45892 Longitude 103.15348

NATURE OF RELEASE

Type of Release: Natural Gas and liquid	Volume of Release: Approximately 2 Barrels of liquid and 452.8mcf of natural gas by calculation.	Volume Recovered: NONE
Source of Release: Vehicle hit 4 inch vent on a 16 inch natural gas gathering line with 14 lbs. of pressure and 4mmcf of volumn.	Date and Hour of Occurrence: 12:30PM March 16,2010	Date and Hour of Discovery 2:00PM PM March 16,2010
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES. To Whom? Larry Johnson OCD in Hobbs by phone and to OCD on call phone	
By Whom? Roger Holland	Date and Hour 2:00PM March 16,2010	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES. Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken. * 4 inch vent on a natural gas gathering line was hit by a vehicle. Line was excavated and leak repaired.		
Describe Area Affected and Cleanup Action Taken.* The area was affected by a light overspray on grass and mesquite. The area was sprayed with micro-blaze.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION 	
Printed Name: Don Embrey	Approved by District Supervisor ENVIRONMENTAL ENGINEER	
Title: Training Specialist	Approval Date: 4.6.10	Expiration Date: —
E-mail Address: dembrey@targaresources.com	Conditions of Approval:	
Date: March 18, 2010 Phone: (432) 688-0546	Attached <input type="checkbox"/> IRP# 10-4-2469	

* Attach Additional Sheets If Necessary