

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

MAR 16 2010

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report

☐ Final Report

Name of Company BOPCO, L.P. *260737* Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Telephone No. 432-556-8730
Facility Name Poker Lake Unit #158 Facility Type E&P API 30-015-31690

Surface Owner Federal Mineral Owner Federal Lease No.

30015 31690
LOCATION OF RELEASE
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County
A 7 24S 30E *6660* *6660* *6660* Eddy

Latitude N 32.237400 Longitude W 103.914150

NATURE OF RELEASE

W-7100

Type of Release: Crude oil and produced water Volume of Release: 5 Bbls of Produced water and 45 Bbls of Crude oil Volume Recovered: 40 Bbls
Source of Release: Tank overflow Date and Hour of Occurrence 3/8/10 Approximately 2:30 p.m. Date and Hour of Discovery 3/8/10 4:30 p.m.
Was Immediate Notice Given? ☒ Yes ☐ No ☐ Not Required If YES, To Whom? Randy, emergency NMOCD number
By Whom? *Tony Savoie* Date and Hour 3/9/10 12:04 p.m.
Was a Watercourse Reached? ☐ Yes ☒ No If YES, Volume Impacting the Watercourse.

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A valve on the produced water tanks was left open while the operator was tending to other activities, the source of the overflow was corrected and a vacuum truck was dispatched to the area to remove the fluid inside of the earthen containment.
Describe Area Affected and Cleanup Action Taken.* The entire area of the earthen containment was covered with crude oil, approximately 4500 sq. ft. The free standing oil was removed and the saturated area around the tanks inside the containment was covered with dry dirt to allow for normal operations to continue. Approximately 30,600 sq. ft. of pasture land was affected by a fine mist of crude oil due to the excessive winds that day. The affected vegetation was washed down with a nutrient and microblaze solution.
The Site remediation for the produced water and crude oil spill will follow the NMOCD guidelines for leaks and spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: *Tony Savoie* OIL CONSERVATION DIVISION
Printed Name: Tony Savoie Approved by District Supervisor: *[Signature]* Remediation Actions to be completed and Final C-141 submitted with confirmation analyses/documentation on or before the Expiration Date.
Title: Waste Mgmt. & Remediation Specialist Approval Date: *4-8-10* Expiration Date: *6-8-10*
E-mail Address: TASavoie@BassPet.com Conditions of Approval: Attached ☐
Date: 3/15/10 Phone: 432-556-8730 Notify OCD 48 hours prior to obtaining samples where analyses are to be presented to OCD *222-400*

* Attach Additional Sheets If Necessary