

RECEIVED

MAY 05 2010

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

HOBBS

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action**OPERATOR**
☐ Initial Report ☒ Final Report

Name of Company	<i>Ranger 40</i>	Contact	<i>Alan Standefer</i>
Address	<i>1004 Collier Way Suite Naples FL</i>	Telephone No.	<i>432-557-8072</i>
Facility Name	<i>Satellite #3</i>	Facility Type	<i>Fluid Transfer Line</i>
Surface Owner	Mineral Owner		Lease No.

LOCATION OF RELEASE API# 30-025-23883-00-00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>F</i>	<i>5</i>	<i>25S</i>	<i>37E</i>	<i>N/A</i>	<i>N/A</i>	<i>N/A</i>	<i>N/A</i>	<i>Lea</i>

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	<i>Produced water / oil</i>	Volume of Release	<i>30</i>	Volume Recovered	<i>25 BBL</i>
Source of Release	<i>Fluid Transfer Line</i>	Date and Hour of Occurrence	<i>1-22</i>	Date and Hour of Discovery	<i>1-22</i>
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required		If YES, To Whom?	<i>1:00p.m. OGD & Land owner</i>	
By Whom?	<i>Alan Standefer</i>		Date and Hour	<i>1-23-2010</i>	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		If YES, Volume Impacting the Watercourse.		

If a Watercourse was Impacted, Describe Fully.*

none

Describe Cause of Problem and Remedial Action Taken.*

Fluid transfer line blowout causing oil and produced water to be leaked into pasture. Around 30 BBL spilled sucked up liquid scraped top and hauled off to Sundance for disposal - recovered 25 BBLs of liquid

Describe Area Affected and Cleanup Action Taken.*

Pasture East of North T.B. was affected. did initial trench sampling per OGD request realized there was a caliche cap was given permission by geoffrey lech to excavate 1-2' to caliche and then backfill Hauled out 41 loads Hauled in 45 loads

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature.	<i>Alan Standefer</i>			OIL CONSERVATION DIVISION	
Printed Name:	<i>Alan Standefer</i>			ENV. ENGINEER:	
Title.	<i>Contract Pumpin</i>			Approved by District Supervisor: <i>Jeffrey Lech</i>	
E-mail Address:				Approval Date.	<i>05/07/10</i>
Date:				Expiration Date	<i>-</i>
Phone:	<i>(432) 557-8722</i>			Conditions of Approval:	Attached <input type="checkbox"/>
				<i>IRP-10-3-2448</i>	

* Attach Additional Sheets If Necessary