


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-00802

Release Notification and Corrective Action

NMB1016047457

OPERATOR

☒ Initial Report

☐ Final Report

Name of Company Devon Energy	Contact Robert Bell, Foreman
Address 6488 Seven Rivers Hwy - P.O. Box 250	Telephone No. 575-748-7448
Facility Name WRL State #1	Facility Type

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter M	Section 6	Township 18s	Range 27E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------------------	---------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	-----------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 50 bbls	Volume Recovered 50 bbls
Source of Release Water transfer line ruptured	Date and Hour of Occurrence 05/19/10 - 2:45 pm	Date and Hour of Discovery 05/19/10 - 2:45 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Todd Suter	
By Whom? Tommy Polly, Assistant Foreman	Date and Hour 05/19/10 - 4:45	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* 4" water transfer line ruptured & released 50 BBLS of produced water.		
Describe Area Affected and Cleanup Action Taken.* Approximately 50 BBLS of produced water ran down draw. Contacted BLM rep & was instructed to flush draw with 100 BBLS of fresh water. We flushed draw with 390 BBLS of fresh water. Total water recovered was 350 BBLS		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: Mykol Horner	OIL CONSERVATION DIVISION	
Printed Name: Mykol Horner	Approved by District Supervisor: [Signature]	
Title: Field Tech 1	Approval Date: JUN 09 2010	Expiration Date:
E-mail Address: mykol.horner@dvn.com	Conditions of Approval: REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: June 30, 2010	Attached <input checked="" type="checkbox"/>
Date: 05/24/10 Phone: 575-748-0160		

* Attach Additional Sheets If Necessary

NMB1016047457

2RP-418