

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUN 28 2010

HOBBSOCD

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Targa Midstream Services L P	Contact: James Lingnau 575.394.2534, Chuck Tolsma 575.631 6026
Address: PO Box 1909 Eunice, NM 88231	Telephone No. (575) 394-2534
Facility Name: Eunice North Compressor Station	Facility Type: Natural Gas Compression
Surface Owner: Targa Resources	Mineral Owner: <u>API</u> Lease No. <u>30.025.21491</u>

LOCATION OF RELEASE

Unit Letter	Section 28	Township 21S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.45158 Longitude 103.16323

WTR. 45-50'

NATURE OF RELEASE

Type of Release: Condensate and oil in drains	Volume of Release: Unknown, possibly 5 to 10 Barrells	Volume Recovered: Most of Liquid
Source of Release: Compressor Station drain system	Date and Hour of Occurrence: 4 PM June 20, 2010	Date and Hour of Discovery 4 PM June 20, 2010
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson OCD in Hobbs by phone	
By Whom? Don Embrey	Date and Hour 10 AM June 21, 2010	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken. *

Rain of 2 1/2 inches in a 1 hour period. Lightning disrupted purchase power and pumps were down. Drain system overflowed to South side of engine room. Liquid was contained and recovered with vacuum truck. Contaminated soil will be excavated and disposed of in an OCD approved landfarm.

Describe Area Affected and Cleanup Action Taken *

Vacuum truck was called on site after storm. The area affected had the liquid recovered by a vacuum truck and the contaminated soil will be excavated and hauled to an OCD approved landfarm. The area will be excavated, sampled, and soil contamination disposed of to insure compliance with OCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Don Embrey</u>	OIL CONSERVATION DIVISION	
Printed Name: Don Embrey	Approved by District <u>Supervisor</u> ENVIRONMENTAL ENGINEER	
Title: Training Specialist	Approval Date: <u>6.28.10</u>	Expiration Date: <u>8.30.10</u>
E-mail Address: dembrey@targaresources.com	Conditions of Approval.	
Date: June 22, 2010 Phone: (432) 688-0546	Submitted Final C-141 w/ Docs By <u>IRP# 10.6.2572</u>	

* Attach Additional Sheets If Necessary

n LWJ1017951562
PLWJ1017952227