

1R - 427-06

REPORTS

DATE:

7-2-10

L. Peter Galusky, Jr. Ph.D., P.G.

Texerra

**505 N Big Spring, Suite 404 Midland, Texas 79701
Tel: 917-339-6791 E-mail: lpg@texerra.com**

July 2nd, 2010

Mr. Edward Hansen
New Mexico Energy, Minerals, & Natural Resources
Oil Conservation Division, Environmental Bureau
1220 S. St. Francis Drive
Santa Fe, New Mexico 87505

RECEIVED

JUL 12 2010

Environmental Bureau
Oil Conservation Division

Re: Monitor Well Plugging & Abandonment Report
NMOCD Case Number: 1R427-06
EME O-19 Jct, UL O Sec 19 T 20S R 37E
Rice Operating Company

Sent via E-mail and Certified U.S. Mail w Return Receipt No. 7008 1830 0004 2694 4248

Mr. Hansen:

Please be advised that Rice Operating Company has plugged and abandoned the monitor wells (MW-1 and MW-2) located at the EME O-19 Jct site per the specifications given in the NMOCD notice of termination sent via e-mail on April 15th, 2010. These monitor wells were plugged on May 13th, 2010 with cement grout containing between 1% to 3% bentonite (see attached driller's report). With this action we understand that Rice Operating Company has fulfilled their requirements under 19.15.29 NMAC for this project.

Rice Operating Company is the service provider (agent) for the EME Salt Water Disposal (SWD) System and has no ownership of any portion of pipeline, well or facility. The EME SWD System is owned by a consortium of oil producers, System Parties, who provide all operating capital on a percentage ownership/usage basis.

Thank you for your consideration.

Sincerely,



L. Peter Galusky, Jr. Ph.D.

Copy: Rice Operating Company

HARRISON & COOPER, INC.

Drilling & Pump Professionals

Ph: (806) 866-4026

Fax: (806) 866-4044

harrisoncooper-drilling.com

7414 85th Street, Lubbock, Texas 79424-4951

P.O. Box 96, Wolforth, Texas 79382-0096

Plugging Report

Client	Rice Operating
Contractor	Harrison & Cooper
Date Completed	5/13/2010
Site	EME Jct. O-19
Well ID	MW-1
Casing Diameter	2"
Well Depth	39'
Casing Material	PVC
Plugging Material	Portland/Bentonite Slurry
Slurry Interval	3'-39'
Cement Interval	0'-3'

Copies: File

Email (Hack Conder)

Mail (Rice-Hobbs)

Regulated by: Texas Dept. of Licensing & Regulation, Water Well Division, P.O. Box 12157, Austin, TX 78711, (800) 803-9202

EME O-19 P&A report for MW-1.

HARRISON & COOPER, INC.

Drilling & Pump Professionals

7414 85th Street, Lubbock, Texas 79424-4951

P.O. Box 96, Wolfforth, Texas 79382-0096

Ph: (806) 866-4026

Fax: (806) 866-4044

harrisoncooper-drilling.com

Plugging Report

Client	Rice Operating
Contractor	Harrison & Cooper
Date Completed	5/13/2010
Site	EME Jct. O-19
Well ID	MW-2
Casing Diameter	2"
Well Depth	39'
Casing Material	PVC
Plugging Material	Portland/Bentonite Slurry
Slurry Interval	3'-39'
Cement Interval	0'-3'

Copies: File
Email (Hack Conder)
Mail (Rice-Hobbs)

Regulated by: Texas Dept. of Licensing & Regulation, Water Well Division, P.O. Box 12157, Austin, TX 78711, (800) 803-9202

EME O-19 P&A report for MW-2.



EME O-19 - Photographs of monitor well plugging & abandonment.