

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JUN 01 2010

HOBBSD

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Lynx Operating Company	Contact: Ed Pittinger
Address: 600 N. Marienfeld, Suite 918, Midland, TX 79701	Telephone No.: 432-686-2101
Facility Name: Pat McClure "A" Battery	Facility Type: Production Battery

Surface Owner: Unknown	Mineral Owner: Various	Lease No.: Fee
------------------------	------------------------	----------------

LOCATION OF RELEASE APL # 30-025-05315-06-00

Unit Letter G	Section 14	Township 15S	Range 37E	Feet from the ~1650	North/South Line North	Feet from the ~2310	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	------------------------	---------------------------	------------------------	------------------------	---------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: Unknown (<25 Bbls.)	Volume Recovered: None
Source of Release: Produced Water Tank	Date and Hour of Occurrence 3/23/10 Overnight	Date and Hour of Discovery 3/23/10 Morning
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

The water transfer pump malfunctioned and the water tank overflowed. All fluid was contained within the tank battery berm.

Describe Area Affected and Cleanup Action Taken.\*

Plans are underway and activities have begun to dismantle the battery and move it approximately 200 ft. from the current site. This will facilitate the removal of any contaminated soil and its replacement with fresh soil. Any removed soil will be disposed of at an approved site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Edward J. Pittinger	Approved by District Supervisor: 	
Title: Sr. VP and COO	Approval Date: 06/01/10	Expiration Date: 08/02/10
E-mail Address: epittinger@lynxco.biz	Conditions of Approval: DISMANTLE TANK BATTERY. DELINEATE TO CLEAN + 1. SUBMIT FINAL	Attached <input type="checkbox"/>
Date: 5/26/10 Phone: 432-686-2101	IRP-10-9-2619	

\* Attach Additional Sheets If Necessary

C-141 BY 08/02/10.