

District I
1625 N. French Dr. Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr. Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

SEP 29 2010

Form C-141
Revised October 10, 2003

NMOCD ARTESIA

Submit 2 copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

NMLB1027336691

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amanda Trujillo
Address 104 S 4 TH Street	Telephone No. 575-748-1471	
Facility Name Cooper AHH #1 Battery	API Number 30-015-26299	Facility Type Battery
	Order Number 2RP-439	
Surface Owner fee	Mineral Owner fee	Lease No.

LOCATION OF RELEASE

Unit Letter F	Section 1	Township 20S	Range 24E	Feet from the 1650	North/South Line NORTH	Feet from the 1650	East/West Line WEST	County EDDY
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude N33 13240 Longitude W104 13323

NATURE OF RELEASE

Type of Release WATER	Volume of Release 925	Volume Recovered 910
Source of Release Nipple on discharge of water pump blow out	Date and Hour of Occurrence 8/17/2010	Date and Hour of Discovery 8/17/2010 - PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD/Artesia	
By Whom? Amanda Trujillo - Yates Petroleum Corporation	Date and Hour 8/18/2010 pm 9/3/10 11:57 AM email ME	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully * N/A		

Describe Cause of Problem and Remedial Action Taken.*

Nipple on discharge of water pump broke. Closed valves and repaired damage. Vacuum trucks and clean up crew was dispatched immediately to make necessary repairs and remedial steps

Describe Area Affected and Cleanup Action Taken.*

An approximate size of 125' x 50' was impacted. The impacted area is located within the battery around the storage tanks. Soil from the pooling areas was excavated and disposed of at an NMOCD approved facility. Vertical and horizontal delineation samples will taken and analysis ran for TPH and BTEX once all contaminated material has been removed. Chlorides analysis upon request. Depth to Ground Water: >100' (approx. 286' per New Mexico State Engineers Office); Wellhead Protection Area: No; Distance to Surface Water Body: >1000'; SITE RANKING IS 0. Based on site ground water quality and enclosed analytical results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state or local laws and/or regulations.

Signature: A Trujillo

Printed Name: Amanda Trujillo

Title: Environmental Scientist

E-mail Address: atrujillo@yates-petroleum.com

Date: Wednesday, September 29, 2010

Phone: 575-748-4310

Attach Additional Sheets If Necessary

OIL CONSERVATION DIVISION

Signed By: Mike Bratcher
Approved by District Supervisor

SEP 30 2010

Approval Date

Expiration Date:

Conditions of Approval:

Attached ☐

REMEDATION per OCD Rules and
Guidelines. SUBMIT REMEDIATION
PROPOSAL BY: 10/30/10

Chloride analysis Required

2RP-439

NMLB1027337331

Bratcher, Mike, EMNRD

From: Amanda Trujillo [atrujillo@yatespetroleum.com]
Sent: Wednesday, September 29, 2010 2:33 PM
To: Bratcher, Mike, EMNRD
Subject: FW: Cooper AHH #1 Battery
Attachments: Cooper AHH #1 (8-17-2010 Initial)r.pdf

Mr. Bratcher:

Attached is the C-141.

Thank you,

Amanda N. Trujillo
Environmental Scientist
Yates Petroleum Corporation
Office 575-748-4310
Cell 575-703-6537
Email atrujillo@yatespetroleum.com

-----Original Message-----

From: Amanda Trujillo
Sent: Friday, September 03, 2010 11:57 AM
To: 'Bratcher, Mike, EMNRD'
Cc: Jerry Fanning
Subject: Cooper AHH #1 Battery

Mr. Bratcher:

Yates Petroleum reports a release at the following location:

Cooper AHH #1 and #2 Battery
Section 1, Township 20 South, Range 24 East
Eddy County
Date of Release: 08-17-2010
Approximately 925 barrels of water were released 910 barrels recovered
Cause of release has been isolated and repairs have been made
The release was contained within the berms and a vacuum truck on site recovered standing fluids
Site will be evaluated and a work plan for remediation will be submitted for consideration.

If you should have any questions please feel free to contact me at the number below.

Amanda N. Trujillo
Environmental Scientist
Yates Petroleum Corporation
Office 575-748-4310
Cell 575-703-6537
Email atrujillo@yatespetroleum.com

Bratcher, Mike, EMNRD

From: Amanda Trujillo [atrujillo@yatespetroleum.com]
Sent: Friday, September 03, 2010 11:57 AM
To: Bratcher, Mike, EMNRD
Cc: Jerry Fanning
Subject: Cooper AHH #1 Battery

Mr. Bratcher:

Yates Petroleum reports a release at the following location:

Cooper AHH #1 and #2 Battery
Section 1, Township 20 South, Range 24 East
Eddy County
Date of Release: 08-17-2010
Approximately 925 barrels of water were released 910 barrels recovered
Cause of release has been isolated and repairs have been made
The release was contained within the berms and a vacuum truck on site recovered standing fluids
Site will be evaluated and a work plan for remediation will be submitted for consideration.

If you should have any questions please feel free to contact me at the number below.

Amanda N. Trujillo
Environmental Scientist
Yates Petroleum Corporation
Office 575-748-4310
Cell 575-703-6537
Email atrujillo@yatespetroleum.com