RECEIVED JUL 1 6 2010

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztee, NM 87410
District IV
1220 S. St. Francis-Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

30-015	- 317	90	Rele	ease Notifi	catio	n and Co	orrective A	ction	4766 2920929999999999999999999999999999999	*****		
nMLB 1030158102				OPERATOR				[🛛 Initi	al Report		Final Report
Name of Company COG OPERATING LLC 229/37				137	Contact Pat Ellis							
Address 550 W. Texas, Suite 100, Midland, TX 79701)1	Telephone No. 432-230-0077							
Facility Nar	ne	Beech Feder	al #2 Ta	nk Battery		Facility Typ	e Tanl	k Battery	1			
Surface Owner Federal Mineral Owner				Owner				Lease N	No. NI	MLC-0	58181	
				LOCA	ATIO	N OF RE	LEASE					
Unit Letter	Section	Township	Range	Feet from the	North				County	County		
J	25	178	27E					Eddy				
	**************************************		<u></u>	Latitude 32	48.140	Longiti	ude 104 13.725					
				NAT	TURE	OF REL	EASE					
Type of Rele		oduced Water							Recovered 23bbls			
Source of Re	lease H	eater Treater				Date and Hour of OccurrenceDate and Hour of Discovery07/04/201007/04/20109:00 a.m.						
Was Immedi	ate Notice (Yes 🛛	No 🖾 Not R	equired	lf YES, To	Whom?					
By Whom?					Date and Hour							
Was a Watercourse Reached?					If YES, Volume Impacting the Watercourse.							
If a Watercou	irse was lin	pacted, Deser	ibe Fully.	*								
Describe Cau	ise of Probl	em and Reme	dial Actio	n Taken.*							~	
Heater treate	r fire tube g	gasket failed.	The heate	r treater fire tube	gasket l	as been repla	ced and the heater	r treater h	as been p	ut back into	servic	е.
Describe Are	a Affected	and Cleanup a	Action Ta	ken.*								
where the flu contained ins R27E, 1650'	id pooled b ide the fire FSL 1650'	wehind the heat wall of the fac FEL, 32.8023	ter treater. Sility. (Th	All free fluids w e closest well loc 4.229053). Tetra	vere rec ation to Tech w	overed. The d the release is ill sample the	ter, we were able limensions of the the Beech Federa spill site area to c al prior to any sig	pooling a d #2, AP# lelineate a	rea was 2 # 30-015- iny possil	0' x 40'. A -31790, Uni ble contami	ll fluid it J, Sec	was , 25-T17S-

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

	7	>	OIL CONSERVATION	DIVISION				
Signature:				Approved by DSigned Byvisor.				
Printed Name: Josh Russo								
_Title:	HSE Coordinator		Approval Date: 0CT 28 2010 Expiration I	Date:				
E-mail Address:	jrusso@conchoresourc	es.com	Conditions of Approval: Remediation per NHOCOS Rules & Gaudelines	Attached				
Date: 07/16/201	0 Phone:	432-212-2399	NMOCO Pules + Guidelines					
* Attach Additional	Sheets If Necessary		Remediation proposed approved 10/28/10	2RP 1/5Z				
				N11-432				

Bratcher, Mike, EMNRD

From:	Joshua Russo [jrusso@conchoresources.com]
Sent:	Friday, July 16, 2010 9:07 AM
To:	Bratcher, Mike, EMNRD; james_amos@nm.blm.gov
Cc:	Pat Ellis; Tavarez, Ike
Subject:	Beech Federal #2 Tank Battery C-141 Initial Report
Attachments:	BEECH FEDERAL #2 TANK BATTERY DATE OF RELEASE 07-04-2010.PDF

Gentlemen,

Please find attached the C-141 Initial Report for the Beech Federal #2 Tank Battery. If you have any questions or concerns feel free to contact me.

Thank you,

Joshua Russo

HSE Coordinator 550 W. Texas Ave, Suite 100 Midland, Texas 79701 Phone: (432) 683-7443 Cell: (432) 212-2399 jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.