

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Brigham H #3	Facility Type	Well

Surface Owner	Federal	Mineral Owner		Lease No. (API#)	30-015-30677
---------------	---------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	21	17S	30E					Eddy

Latitude 32 49.208 Longitude 103 58.965

NATURE OF RELEASE

Type of Release	Produced fluid	Volume of Release	20bbls	Volume Recovered	18bbls
Source of Release	Flowline	Date and Hour of Occurrence	02/01/2011	Date and Hour of Discovery	02/01/2011 4:00 p.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Hot oiler was pumping down a flowline that had a small hole in it. The hot oiler truck immediately stopped and the flowline was patched. Since then the patched joint of flowline has been replaced with a new joint.

Describe Area Affected and Cleanup Action Taken.*

Initially 20bbls of produced fluid was released from the flowline and we were able to recover 18bbls with a vacuum truck. The fluid traveled 10' x 50' to a low area in pasture measuring 20' x 20'. All standing fluid was recovered with the vacuum truck. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name:	Josh Russo	Approved by District Supervisor:	<i>Mike Brannan</i>
Title:	HSE Coordinator	Approval Date:	2/17/11
E-mail Address:	jrusso@conchoresources.com	Expiration Date:	
Date:	02/11/2011	Phone:	432-212-2399
		Conditions of Approval:	Attached <input type="checkbox"/>
		Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	

* Attach Additional Sheets If Necessary

3/17/11

2RP-606

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@conchoresources.com]
Sent: Monday, February 14, 2011 12:50 PM
To: Bratcher, Mike, EMNRD; terry_gregston@nm.blm.gov
Cc: Pat Ellis; james_amos@nm.blm.gov; Tavaréz, Ike; Dorey, Kim; tom.k.franklin@tetrattech.com
Subject: C-141 - Brigham H #3
Attachments: BRIGHAM H #3 FLOWLINE INITIAL.PDF

Please see attached the C-141 Initial Report for a release we had at the Brigham H #3.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.