

GW - 028

MONITORING REPORT

Annual GW Monitoring Rep


MAPS

(Feb 2011)



LEGEND:

- DRO GROUNDWATER EXCEEDANCE AREA
- MONITORING WELL
- RECOVERY WELL
- IRRIGATION WELL
- ABANDONED WELL



NAVAJO REFINING COMPANY
ARTESIA REFINERY, EDDY COUNTY, NEW MEXICO
2010 ANNUAL GROUNDWATER REPORT
**DRO CRITICAL GROUNDWATER
SCREENING LEVEL EXCEEDANCE AREAS
FIRST SEMI-ANNUAL EVENT 2010**



FIGURE
9