


# GW - 028 MONITORING REPORT Annual GW Monitoring Rep MAPS (Feb 2011)



## LEGEND:

- ARSENIC GROUNDWATER EXCEEDANCE AREA
- MONITORING WELL
- RECOVERY WELL
- IRRIGATION WELL
- ABANDONED WELL



NAVAJO REFINING COMPANY  
ARTESIA REFINERY, EDDY COUNTY, NEW MEXICO  
**2010 ANNUAL GROUNDWATER REPORT**  
**ARSENIC CRITICAL GROUNDWATER  
SCREENING LEVEL EXCEEDANCE AREAS  
FIRST SEMI-ANNUAL EVENT 2010**



FIGURE  
**11**