

GW - 028

MONITORING REPORT

Annual GW Monitoring Rep


MAPS

(Feb 2011)



LEGEND:

- BENZENE GROUNDWATER EXCEEDANCE AREA
- MONITORING WELL
- RECOVERY WELL
- IRRIGATION WELL
- ABANDONED WELL



NAVAJO REFINING COMPANY
ARTESIA REFINERY, EDDY COUNTY, NEW MEXICO

2010 ANNUAL GROUNDWATER REPORT

BENZENE CRITICAL GROUNDWATER SCREENING LEVEL EXCEEDANCE AREAS SECOND SEMI-ANNUAL EVENT 2010



FIGURE

14