

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company Devon Energy	6137	Contact <input type="checkbox"/> Ernie Duran
Address P. O. Box 250 Artesia, NM 88211		Telephone No. <input type="checkbox"/> 575-513-1768
Facility Name TNT 6 Federal #1		Facility Type <input type="checkbox"/> Oil Well

Surface Owner	Mineral Owner	Lease No. <input type="checkbox"/>
---------------	---------------	------------------------------------

**LOCATION OF RELEASE**

Unit Letter	Section 6	Township 17S	Range 29E	Feet from the 660	North/South Line South	Feet from the 1980	East/West Line East	County Eddy County, NM
-------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------------------

**NATURE OF RELEASE**

Type of Release 10 BO and 13 BPW	Volume of Release 23 BBLs	Volume Recovered <input type="checkbox"/> 15 BBLs
Source of Release Overflowed tanks.	Date and Hour of Occurrence 2-2-11 8:00 AM	Date and Hour of Discovery <input type="checkbox"/> 2-2-11 8:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos BLM - Carlsbad	
By Whom? <input type="checkbox"/> Ernie Duran	Date and Hour <input type="checkbox"/> 2-2-11 3:30 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*  N/A
--

Describe Cause of Problem and Remedial Action Taken.* Crew working on pumping unit left it pumping did not tell Lease Operator and over ran tanks.
---

Describe Area Affected and Cleanup Action Taken.* 40'x140' area on location pad, 1' x 160' off pad. Will rake, till, and fertilize the area.
---

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Adrienne Verkler</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Adrienne Verkler	Signed By <i>M. L. Brannan</i>	
Title: Field Tech II	Approved by <input type="checkbox"/> District Supervisor:	
Date: 2-3-11 Phone: (575) 748-0174	Approval Date: 3/3/11	Expiration Date:
Conditions of Approval:		Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules &  
Guidelines. **SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:**

4/3/11

2 RP-614

