

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

MAR 10 2011

NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report



Name of Company	COG OPERATING LLC 229/37	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Dogwood Federal	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#)	30-015-32927 NMNM-94594

LOCATION OF RELEASE

Unit Letter F	Section 25	Township 17S	Range 27E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32 48.351 Longitude 104 14.115

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	10bbls	Volume Recovered	8bbls
Source of Release	Water tank	Date and Hour of Occurrence	03/01/2011	Date and Hour of Discovery	03/01/2011 3:30 p.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* Water haulers failed to pick up water after the well was turned back on.					
Describe Area Affected and Cleanup Action Taken.* Initially 10bbls was released from the water tank and we were able to recover 8bbls with a vacuum truck. The entire release was contained inside the facility berm walls and it measure and area of 3' x 50'. All standing fluid has been removed and contamination has been dug out. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD / BLM for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Josh Russo		Signed By:  Approved by District Supervisor:			
Title: HSE Coordinator		Approval Date: 3/16/11		Expiration Date:	
E-mail Address: jrusso@conchoresources.com		Conditions of Approval:		Attached <input type="checkbox"/>	
Date: 03/10/2011 Phone: 432-212-2399		REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: 4/16/11			

\* Attach Additional Sheets If Necessary

2RP-642

## Bratcher, Mike, EMNRD

---

**From:** Joshua Russo [jrusso@conchoresources.com]  
**Sent:** Thursday, March 10, 2011 9:54 AM  
**To:** Bratcher, Mike, EMNRD; terry\_gregston@nm.blm.gov  
**Cc:** Pat Ellis; james\_amos@nm.blm.gov; Tavaréz, Ike; Dorey, Kim; tom.k.franklin@tetrattech.com  
**Subject:** C-141 - Dogwood Federal TB  
**Attachments:** DOGWOOD FEDERAL TANK BATTERY -- DATE OF RELEASE -- 03-01-2011.PDF

Please see attached the C-141 Initial Report for a release that occurred at the Dogwood Federal TB on 03/01/2011.

Thank you,

### Joshua Russo

HSE Coordinator  
550 W. Texas Ave, Suite 100  
Midland, Texas 79701  
Phone: (432) 683-7443  
Cell: (432) 212-2399  
[jrusso@conchoresources.com](mailto:jrusso@conchoresources.com)



**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.