

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
JAN 27 2010
NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Yates Drilling company 25575 Contact Greg Boans
Address 105 South 4th Street, Artesia, NM 88210 Telephone No. 575-748-5363
Facility Name Robinson "B" Federal #1 Facility Type Tank Battery

Surface Owner BLM Mineral Owner Lease No. LC-064073

LOCATION OF RELEASE

Unit Letter F	Section 34	Township 17S	Range 29E	Feet from the 2310	North/South Line North	Feet from the 2310	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	-------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 18 bbls	Volume Recovered 10 bbls
Source of Release Gun Barrel Water Leg	Date and Hour of Occurrence 1:30 PM, 1/22/10	Date and Hour of Discovery 2:00 PM, 1/22/10
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, NMOCO Bobby Ballard, BLM Carlsbad, NM	
By Whom? Greg Boans	Date and Hour 2:08 PM, 1/22/10	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*


Vacuum trucked recovered 10 bbls fluid and hauled to disposal. Recovered contaminated soil (about 30 yds) and hauled to Lea County Land Farm.

Describe Area Affected and Cleanup Action Taken.*

Repaired water leg.

Removed recovered fluid and remediated contaminated soil to Lea Land Farm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 

Printed Name: Greg Boans

Title: Production Supervisor

E-mail Address: greg@yates petroleum.com

Date: 1/26/2010 Phone: 575-748-5363

OIL CONSERVATION DIVISION

Approved by District Supervisor Signed By 

Approval Date: 3/21/11

Expiration Date:

Conditions of Approval:
Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

Attached ☐

* Attach Additional Sheets If Necessary

2RP-650

4/21/11