

**CORRECTED COPY**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 <sup>TH</sup> Street	API Number 30-015-32896	Telephone No. 575-748-1471
Facility Name Mimosa Federal SWD #3Y		Facility Type Battery

Surface Owner Federal	Mineral Owner Federal	Lease No. NM-39635
--------------------------	--------------------------	-----------------------

**LOCATION OF RELEASE**

Unit Letter P	Section 4	Township 20S	Range 24E	Feet from the 635'	North/South Line South	Feet from the 330'	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.59732 Longitude 104.58540

**NATURE OF RELEASE**

Type of Release Oil	Volume of Release 20 B/O	Volume Recovered 0 B/O
Source of Release Sales Line	Date and Hour of Occurrence 2/20/2011; AM	Date and Hour of Discovery 2/20/2011; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*

Sales line collar came apart to cause release. Shut in valves and line was repaired.

Describe Area Affected and Cleanup Action Taken.\*

An approximate area of 30' X 500' (outside of battery). No oil was recovered. Entire release area has been sprayed with Microblaze. Vertical and horizontal delineation samples have been taken (3/9/2011) and analysis to be run for TPH & BTEX. Based on results a work plan will be submitted to address remedial actions to be taken. Depth to Ground Water: >100' (approximately 268', per NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: 200-1000', SITE RANKING IS 10.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: 

Printed Name: Robert Asher

Title: Environmental Regulatory Agent

E-mail Address: boba@yatespetroleum.com

Date: Wednesday, March 09, 2011

Phone: 575-748-4217

Signed By   
Approved by District Supervisor:

Approval Date: 3/16/11

Expiration Date:

Conditions of Approval:

Attached ☐

REMEDATION per OCD Rules and  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL BY:

4/16/11

2 RP-643

\* Attach Additional Sheets If Necessary