

French Dr., Hobbs, NM 88240
District II
W. Grand Avenue, Artesia, NM 88210
District III
00 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company OXY USA		Contact Kelton Beaird
Address 1502 W. Commerce Carlsbad, NM 88220		Telephone No. (O) 575-628-4100
Facility Name Righthand Canyon 35-1		Facility Type Gas Well
Surface Owner BLM	Mineral Owner BLM	Lease No. 3001526126

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	35	21S	24E					EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil/ Produced Water	Volume of Release 15 oil, 5 water (barrels)	Volume Recovered 5 bbls.
Source of Release Gas line from Horizontal Vessel	Date and Hour of Occurrence	Date and Hour of Discovery 4-30-10 @ 10 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour See above	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.

Stainless steel gas supply line broke. The vessel failed to dump causing the vessel to fill with oil.

Describe Area Affected and Cleanup Action Taken.*

Due to hard rock the surface material was removed and replaced with clean-like material.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Kelton Beaird

Title: HES Specialist

E-mail Address: kelton_beaird@oxy.com

Date: 12-21-10

OIL CONSERVATION DIVISION

Approved by District Supervisor:

Signed By *Mike Beaird*

Approval Date: 4/11/11

Expiration Date:

Conditions of Approval:

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**

Attached ☐

* Attach Additional Sheets If Necessary

5/11/11

2RP-728