


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NKMW 1110339259
Name of Company *Linn Energy* *269324* OPERATOR ☒ Initial Report ☐ Final Report
Address PO Box 69, Loco Hills, NM 88255 Contact Dennis Potter
Facility Name H E West A #29 Telephone No. 575 677 2327
Facility Type Oil Well
Surface Owner BLM Mineral Owner BLM Lease No. NMLC029426-A
API 30-015-28467

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	4	17S	31E					Eddy

Latitude N32.8542 Longitude W103.8706 (in front of electrical panel)

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 25bbls Water	Volume Recovered 15bbls Water
Source of Release Produced Water Line	Date and Hour of Occurrence 27Mar11 0800hrs	Date and Hour of Discovery 27Mar11 0800
Was Immediate Notice Given? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom?	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* The release is a result a produce water line failure. The release occurred and remained inside the walls of the H E West A Battery. Delineation will be performed to determine the depth of penetration of the chlorides. Using the delineation results, a remediation work plan will be submitted to NM OCD and BLM for review and approval.		
Describe Area Affected and Cleanup Action Taken.*		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Dennis Potter</i>	OIL CONSERVATION DIVISION	
Printed Name: Dennis Potter	Approved by District Supervisor: <i>Mike Benavides</i>	
Title: Assistant Production Foreman	Approval Date: <i>4/13/11</i>	Expiration Date:
E-mail Address: dpotter@linenergy.com	Conditions of Approval:	
Date: 11Apr11 Phone: 505 206 7673	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: <i>5/13/11</i>	

* Attach Additional Sheets If Necessary

2RP-742

Bratcher, Mike, EMNRD

From: Vernon Black [vernon@hungry-horse.com]
Sent: Tuesday, April 12, 2011 4:26 PM
To: Bratcher, Mike, EMNRD; tgregsto@blm.gov
Cc: tscarborough@linenergy.com; dpotter@linenergy.com
Subject: Emailing: Initial C 141 H E West A #29
Attachments: Initial C 141 H E West A #29.pdf

Your message is ready to be sent with the following file or link attachments:

Initial C 141 H E West A #29

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.