District 1
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Date: 01/10/11 Phone: 575-390-4186

\* Attach Additional Sheets If Necessary

## State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

2RP-767

Santa Fe, NM 87505													
Release Notification and Corrective Action													
nKmw 1111749957							OPERATOR			☐ Initial Report ☐ Final Repor			
							Contact Natalie Gladden						
							Telephone No. 575-390-4186						
Facility Name Empire Abo L-121							Facility Type Production well						
Surface Owner Unknown Mineral Owner						BLM/OCD			Lease No. 30-015-22062				
LOCATION OF RELEASE													
							South Line   Feet from the   East/West Line   County						
		•	_							-			
Р	3	18S	27E	1186'	FSL		220'	FEL	Eddy				
LatitudeLongitude													
NATURE OF RELEASE													
Type of Release crude oil							Volume of Release 10			Volume Recovered 7			
Source of Release Stuffing box leak										Date and Hour of Discovery 12/28/2010 645am			
Was Immediate Notice Given?  ☐ Yes ☑ No ☐ Not Required							If YES, To Whom? Mike Bratcher and Jim Amos (BLM)						
By Whom? Natalie Gladden Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.						
Yes No													
By Whom? Natalie Gladden  Was a Watercourse Reached?  If Yes No  If a Watercourse was Impacted, Describe Fully.*  Describe Cause of Problem and Remedial Action Taken.*  After a workover on the well, the well was put back onto production, the stuffing box had blown out due to trash in the BPV.													
Describe Cause of Problem and Remedial Action Taken.*													
After a workover on the well, the well was put back onto production, the stuffing box had blown out due to trash in the BPV.													
Describe Area Affected and Cleanup Action Taken.*  Standing fluid was recovered, saturated soil was immediately excavated and hauled off. Site was remediated to NMOCD Standards and the closure													
document will follow.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
federal, state, or local laws and/or regulations.  OIL CONSERVATION DIVISION													
and the state of t							A ,						
Signature: Challe (9) October							and the Karana						
Printed Name	: Natalie C	Approved by Distric Staped Bor: M1/4 Destruction											
Title: EHS E	nvironment	al Tech			Approval Date: 4/27/11 Expiration			Expiration	Date:				
E-mail Addre	ss: natalie.	om		Conditions of Approval:				Attached					

Remediation per OCD Rules &

Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**