


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

n MCB 111235/669

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229/137	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Blackhawk 11 Federal Com #1	Facility Type	Tank Battery

Surface Owner	Federal	Mineral Owner		Lease No. (API#)	30-015-38250
---------------	---------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	11	16S	28E					Eddy

Latitude 32 48.656 Longitude 104 14.099

NATURE OF RELEASE

Type of Release	Produced oil	Volume of Release	10bbls	Volume Recovered	9bbls
Source of Release	Oil tank	Date and Hour of Occurrence	04/25/2011	Date and Hour of Discovery	04/25/2011 7:00 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*




Describe Cause of Problem and Remedial Action Taken.*

An oil tank at the facility ran over due to an increased amount of production overnight. The well has been temporarily shut in, and then the volumes will be curtailed to eliminate reoccurrence in the future.

Describe Area Affected and Cleanup Action Taken.*

Initially 10bbls were released from the oil tank and we were able to recover 9bbls with a vacuum truck. The entire release was completely contained inside the facility walls of the tank battery. This facility is lined with a 40mil liner. Any contaminated gravel will be removed and disposed of appropriately. Clean gravel will be added as necessary. This facility will be returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Josh Russo	Signed By:  Approved by District Supervisor:		
Title: HSE Coordinator	Approval Date: 5/3/2011	Expiration Date: n/a	
E-mail Address: jrusso@conchoresources.com	Conditions of Approval: n/a 	Attached <input type="checkbox"/>	
Date: 04/29/2011	Phone: 432-212-2399		

* Attach Additional Sheets If Necessary

2RP-772

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@conchoresources.com]
Sent: Friday, April 29, 2011 1:54 PM
To: Bratcher, Mike, EMNRD; terry_gregston@nm.blm.gov
Cc: Pat Ellis; james_amos@nm.blm.gov
Subject: C-141 Initial / Final Report
Attachments: img-429142815-0001.pdf

Please see attached the C-141 Initial / Final Report for a release that occurred at a lined facility on 04/25/2011.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.