

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-27438

Release Notification and Corrective Action

NMLB/1125-40973

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company BOPCO, L.P.	260737	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 432-556-8730
Facility Name Poker Lake Unit #79		Facility Type E&P

Surface Owner State of New Mexico	Mineral Owner State of New Mexico	Lease No.B-10679
-----------------------------------	-----------------------------------	------------------


LOCATION OF RELEASE

Unit Letter M	Section 2	Township 25S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.154414 Longitude W 103.857821

NATURE OF RELEASE

Type of Release: Produced water and crude oil	Volume of Release: 40 bbls produced water and 20 bbls crude oil	Volume Recovered: 10 bbls total fluid
Source of Release: Heater Treater	Date and Hour of Occurrence 5/2/11, Hour unknown	Date and Hour of Discovery 5/2/11 10:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher via Voice Mail	
By Whom? Tony Savoie	Date and Hour 5/2/11 10:51 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A gasket failed on the heater treater fire tube. The heater was isolated and crews are working to replace the gasket.

Describe Area Affected and Cleanup Action Taken.*The caliche pad around the pumping well and tank battery location had isolated pockets of produced water and crude oil, the liquid also traveled down a lease road for approximately 360 ft. The entire area of the well pad and battery location was also covered with a fine mist of crude oil and produced water; this was approximately 67,500 sq. ft. The pasture land located to the South West of the battery was also affected with the fine mist of crude oil and produced water; this area was approximately 33,600 sq. ft. All of the free standing fluid was picked up with a vacuum truck. The saturated soil was scraped up and stockpiled on the caliche well pad. The pasture area was left alone. The Site remediation for the produced water and crude oil spill will follow the NMOCD guidelines for leaks and spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by District Supervisor Signed By Mike Bratcher	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: 5/5/2011	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	Attached <input type="checkbox"/>
Date: 5/3/11	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

6/5/2011

2RP-773