

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nkmw 1101256551

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street		Telephone No. 575-748-1471
Facility Name Jackson EM Com. #1	API Number 30-015-21564	Facility Type Battery

Surface Owner Fee	Mineral Owner Fee	Lease No.
----------------------	----------------------	-----------



LOCATION OF RELEASE

Unit Letter O	Section 25	Township 17S	Range 25E	Feet from the 660	North/South Line South	Feet from the 1980	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.80084 Longitude 104.43566

NATURE OF RELEASE

Type of Release Condensate & Produced water	Volume of Release 54 B/C & 9 B/PW	Volume Recovered 0 B/C & 0 B/PW
Source of Release Load line valve	Date and Hour of Occurrence 2/11/2010, PM	Date and Hour of Discovery 2/11/2010, PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD Artesia	
By Whom? Robert Asher/YPC Environmental	Date and Hour 2/12/2010 PM (telephone & e-mail)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Load line valve froze and cracked.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 10' X 25'. No condensate to recover. Vertical/horizontal delineation to determine extent of impacted soils. Work plan to be submitted based on delineation results. Depth to Ground Water: >100' (approx. 150'); Section 25, T17S-R25E; New Mexico Office of the State Engineer), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by District Supervisor 	
Title: Environmental Regulatory Agent	Approval Date: 3/15/2011	Expiration Date:
E-mail Address: boba@yatespetroleum.com	Conditions of Approval:	
Date: Monday, February 22, 2010 Phone: 575-748-4217	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

REMEDATION per OCD Rules and
Guidelines. SUBMIT REMEDIATION
PROPOSAL BY: *Plan submitted*
Remediation in progress

2 RP-550



New Mexico Office of the State Engineer

Wells with Well Log Information

(quarters are 1=NW 2=NE 3=SW 4=SE)
(quarters are smallest to largest) (NAD83 UTM in meters)

POD Number	Sub basin	Use	County	Source	q	q	q	Sec	Tws	Rng	X	Y	Start Date	Finish Date	Log File	Depth Well	Depth Water
RA 02776		DOM	ED	Shallow	1	3	4	24	17S	25E	552658	3631062*	08/25/1951	09/03/1951	09/03/1951	218	
RA 03590		PRO	CH	Shallow	4	4	4	25	17S	25E	553273	3629250*	06/27/1956	06/30/1956	06/27/1956	266	150
RA 04012		DOM	ED	Shallow	3	3	1	23	17S	25E	550224	3631658*	03/04/1959	03/07/1959	03/12/1959	247	171
RA 04170		DOM	ED	Shallow	3	3	4	36	17S	25E	552680	3627635*	04/04/1960	04/08/1960	12/20/1960	207	
RA 04791		PRO	ED	Artesian	3	1	24	17S	25E		551943	3631765*	03/07/1963	03/29/1963	04/04/1963	1107	
RA 05055		STK	ED	Shallow	1	4	35	17S	25E		551160	3628136*	11/08/1964	11/16/1964	12/15/1964	245	185
RA 05286		DOM	ED	Shallow	2	1	3	23	17S	25E	550426	3631456*	11/16/1970	11/20/1970	11/25/1970	285	196

Record Count: 7

PLSS Search:

Section(s): 23, 24, 25, 26, Township: 17S Range: 25E
35, 36

*UTM location was derived from PLSS - see Help

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

2/11/10 3:16 PM

Page 1 of 1

WELLS WITH WELL LOG INFORMATION

FEB-22-2010 MON 05:02 PM YATES ENGINEERING

FAX NO. 15057484585

P. 03

Bratcher, Mike, EMNRD

From: Bob Asher [BobA@yatespetroleum.com]
Sent: Friday, February 12, 2010 1:30 PM
To: Bratcher, Mike, EMNRD
Cc: Jerry Fanning
Subject: Release (Jackson EM Com. #1)

Mike,

Yates Petroleum Corporation is reporting a release caused by a cracked load line valve at the following location that occurred 2/11/2010 at 2:30 PM.

Jackson EM Com. #1
30-015-21564
Section 25, T17S-R25E
Eddy County, New Mexico

Released: 54 B/Condensate & 9 B/PW
Recovered: 0 B/Condensate & 0 B/PW

A site check and evaluation will be conducted and a C-141 Initial Report will be filled at your office.

If you have any questions, please call.

Thank you.



Robert Asher
Yates Petroleum Corporation
boba@yatespetroleum.com
575-748-4217 (Office)
575-365-4021 (Cell)
575-748-4662 (Fax)

This inbound email has been scanned for malicious software and transmitted safely to you using Webroot Email Security.
