

5-USGS-Roswell

1-Laura Richardson-

N.M. OIL CONSERVATION COMMISSION

1-BB, 1-CK-Foreman, 1-Jim-Engr, 1-BW

Form 9-331
Dec. 1973

P. O. BOX 1980

HOBBS, NEW MEXICO 88240

Form Approved.
Budget Bureau No. 42-R1424UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐2. NAME OF OPERATOR
Getty Oil Company3. ADDRESS OF OPERATOR
P.O. Box 730, Hobbs, NM 882404. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
Unit Ltr. C, 330' FNL & 2310' FWL

AT SURFACE:

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐CHANGE ZONES ☐ABANDON* ☐(other) ☐DECEIVED
JUN 15 1982

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 5-3-82 Rigged up & nipped up 8 5/8" csg @ 902' & 5 1/2" 1917-5500'. 10 sacks of cement @ 5100'. Perfs 5147-5396. Plug @ top of 5 1/2" plug @ 910 surface plug. New perfs 3079-3618. Ran 7 7/8" bit & drilled from 0-18'. Ran to 230' & circ. clean.
- 5-4-82 Tag fill @ 230'. 8 5/8" csg in cellar started leaking. Dug out cellar & installed new pipe. Nipped up. Re-ran 7 7/8" bit & drilled mud 230-795'.
- 5-5-82 Drlg. 745-1372'. Drilled mud, cmt & wool. Started circ out side of 8 5/8". Pulled bit. Ran out 8 5/8" 16' below ground.
- 5-6-82 Halliburton pumped in w/ 21 bbls. Ran in & set B.P. @ 60'. Cmt'd with 50 sacks of class "C" containing 3% CaCl. Circ. out cellar flush 1/4 bbl.
- 5-8-82 Drlg. cmt w/ 7 7/8" bit to 45'. Pulled bridge plug @ 60'. Ran 7 7/8" bit to 1372'. Drlg. mud cmt. to 1687' pull to 900'.

Subsurface Safety Valve: Manu. and Type _____

Set @ _____ Ft.

(Cont'd on back)

18. I hereby certify that the foregoing is true and correct

SIGNED D.R. Crockett TITLE Area Superintendent

June 14, 1982

APPROVED BY
CONDITIONS OFACCEPTED FOR RECORD
(ORIG. SGD.) DAVID R. GLASS

APPROVAL, IF ANY:

OCT 21 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

See Instructions on Reverse Side

BEFORE EXAMINED CATANACH

OIL CONSERVATION DIVISION

OCD EXHIBIT NO. 14

CASE NO. 12981