






Oil Conservation Division
Case No. 15235
Exhibit No. 1

Forehand Ranch Cherry Canyon Sands

October 2, 2014




Caza Forehand Rand 27#5




A

Structural Cross Section


A'




Imaging Log Shows Base Channel




Channel cut
from imaging
log



Caza Forehand Ranch 27#5 – Oil Well



Caza Forehand Ranch 27#4 – Pressure Maintenance/SWD



Endurance Forehand Ranch – Pressure Maintenance/SWD 1 ½ Mile North of the Caza Forehand Ranch 27#4

A **30015218550000**
ENDURANCE
FOREHAND


● 2

<1,332FT>


30015221920000
ENDURANCE
FOREHAND

● 3


A'



TD : 5,610
FOREHAND RANCH
CUM OIL : 36,789
CUM GAS : 1,673
CUM WTR : 395,492



TD : 4,000
FOREHAND RANCH
CUM OIL : 6,603
CUM GAS : 0
CUM WTR : 33,381



424,746 Bw injected
since August 2001