

| Well/location Name      | #   | API#         | ACO #   | Date of Last Inspection | Comments  |
|-------------------------|-----|--------------|---------|-------------------------|---|
| Hospah Sand Unit        | 100 | 30-031-20831 | ACO-285 | 10/23/2015              | Requirement to plug by March 15, 2015, Compliance not achieved  |
| Santa Fe Rail Road      | 87  | 30-031-20413 | ACO-285 | 10/23/2015              | Requirement to plug by March 15, 2015, Compliance not achieved  |
| Santa Fe Rail Road      | 97  | 30-031-20855 | ACO-285 | 10/23/2015              | Requirement to plug by March 15, 2015, Compliance not achieved  |
| South Hospah Unit       | 52  | 30-031-20243 | ACO-285 | 10/23/2015              | Requirement to plug by March 15, 2015, Compliance not achieved  |
| South Hospah Unit       | 60  | 30-031-20411 | ACO-285 | 10/23/2015              | Requirement to plug by March 15, 2015, Compliance not achieved  |
| South Hospah Unit       | 39  | 30-031-20152 | ACO-285 | 10/23/2015              | Run Liner in well by January 15, 2015, Compliance not achieved  |
| South Hospah Unit       | 51  | 30-031-20242 | ACO-285 | 10/26/2015              | Requirement to MIT by January 31, 2015, Compliance not achieved |
| Hospah Sand Unit        | 58  | 30-031-20115 | ACO-285 | 10/26/2015              | Requirement to MIT by January 31, 2015, Compliance not achieved |
| Lone Pine Dakota D Unit | 14  | 30-031-20174 | ACO-285 | 10/23/2015              | Requirement to MIT by January 31, 2015, Compliance not achieved |

