

10515



**Trudy Morris**  
Technical Assistant  
New Mexico Team

**MidContinent SBU**  
Chevron North America  
Exploration and Production  
Company  
15 Smith Road  
Midland, Texas 79705  
Tel (432) 687-7364  
Fax (432) 687-7871  
tkmo@chevron.com

February 6, 2006

New Mexico Oil Conservation Division  
1220 South St. Francis Drive  
Santa Fe, New Mexico 87505

Re: **EOR STATUS REPORT**  
Fiscal Year June 1, 2004 – May 31, 2005  
Order # R-9708  
Vacuum Glorieta West Unit  
Lea County, NM

2006 FEB 14 PM 1 00

Gentlemen:

Chevron Corporation, as operator of the Vacuum Glorieta West Unit, submits its annual production report on the Vacuum Glorieta West Unit as required by Rule F1a of the Rules and Procedures for Qualification of Enhanced Oil Recovery Projects and Certification for the Recovered Oil Tax Rate. The project is still a viable EOR project as approved by the Division Order No. R-9708 on August 27, 1992. The Certification of a Positive Production Response was issued on March 7, 1995. The effective date of certification was January 1, 1994.

Attached are production curves of produced oil, gas and water and injected water prior to waterflooding and all years since.

If you have any questions, please call me at (432) 687-7364.

Sincerely,

Trudy Morris  
Technical Assistant  
New Mexico Team

attachment

# VACUUM GLORIETA WEST UNIT

