

29-Jan-08

Well Inspection History

API Number: **30-015-05687-00-00** Well Name & No.: **EAST SHUGART UNIT**
 Operator: **AMERICO ENERGY RESOURCES LLC, PA** District: **ARTESIA** County Name: **EDDY**
 Field: **EAST SHUGART UNIT** Legal: **S: 34 T: 18S R: 31E**
 Well Type: **INJECTION - (ALL TYPES)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
6/25/2007	Phone call	Normal Routine Activity	iGEG0717646		209	Y	
	Operator notified OCD of approx 250 bbl spill of injection water due to parting of injection line.						
4/24/2007	Bradenhead		iGEG0710750		209		
	OK. All Equipment and Location in Good Shape.						
4/10/2007	Routine/Periodic	Normal Routine Activity	iGEG0710043		209	Y	
	No Company Representative to witness Bradenhead test. Well must be shut in pending contact with OCD to reschedule.						
4/17/2006	Bradenhead		iGEG0605344		209		
	OK. All Equipment and Location in Good Shape.						
2/28/2006	File and Compliance Review	Normal Routine Activity	iCLB06059311		212		
	C-141: 2 3/8" flow "T" on the ESU #15 lost partial integrity. The well was shut in to stop release: Flow "T" was then replaced. Area Affected: The area was native pasture w/natural sand dunes. A vaccum truck on location picked up 140 bbl produced H2O from low spot in pasture. Area affected was approx 200'x50'.						
8/22/2005	Bradenhead		iGEG0517439		209		
	OK. All Equipment and Location in Good Shape.						
5/21/2004	Pressure Test	Normal Routine Activity	iMLB04145341		211		
	Witness MIT pressure test to return well to injection. Pressured annulus to 320 psi. Held to 300 psi for 30 min test duration. Closed violation.						
4/23/2004	Compliance Verification	Normal Routine Activity	iMLB04114410		211		
	Well is not being injected into at this time. Flowline valve is closed. Guage on tubing is @ 1200 psi.						
4/6/2004	Bradenhead	Normal Routine Activity	iMLB04090294		211	Y	
	Continuous water flow out int casing valve.						
6/2/2003	Bradenhead		iGEG0312142		209		
	A-OK. All Equipment and Location in Good Shape.						
4/2/2002	Bradenhead		iGEG0202829		209		
	A-OK. All Equipment and Location in Good Shape.						
3/8/2001	Bradenhead		iGEG0101941		209		
	All OK. All Equipment and Location in Good Shape.						
1/12/2000	Pressure Test		iBER0002559		206		
3/4/1999	MIT Witnessed - Other		iBER0001250		206		
	A-OK. All Equipment and Location in Good Shape.						
3/5/1998	MIT Witnessed - Other		iUNK0000018		206		
	A-OK. All Equipment and Location in Good Shape.						
3/6/1997	MIT Witnessed - Other		iGW20030000		206		

Total Inspections Performed: 16

Americo Energy Resources, LLC

**Case 14079
OCD Exhibit No. 4**