

29-Jan-08

#42

Well Inspection History

API Number: **30-015-27670-00-00** Well Name & No.: **EAST SHUGART UNIT**
 Operator: **AMERICO ENERGY RESOURCES LLC, PA** District: **ARTESIA** County Name: **EDDY**
 Field: **EAST SHUGART UNIT** Legal: **S: 34 T: 18S R: 31E**
 Well Type: **INJECTION - (ALL TYPES)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
1/3/2008	Compliance Verification	Normal Routine Activity Spill appears to have been covered with sand.	iGEG0800348		209		
11/19/2007	File and Compliance Review	Normal Routine Activity Final request for remediation plan was sent 10/18/07 after numerous prior requests. No reply has been received. Violation of Rule 116. Further enforcement action will take place if this violation is not addressed prior to the Compliance Action Due Date.	iGEG0732330		209	Y	
8/20/2007	Initial Incident Inspection	Normal Routine Activity C-141 Received.	iGEG0723234		209		
4/24/2007	Bradenhead	Injection Pressure Over Limit. (Rule 703/704 B.)	iGEG0710750		209		
4/24/2007	Routine/Periodic	Normal Routine Activity	iGEG0711433		209		
4/24/2007	Routine/Periodic	Normal Routine Activity	iGEG0711433		209		
4/10/2007	Routine/Periodic	Normal Routine Activity No Company Representative to witness Bradenhead test. Well must be shut in pending contact with OCD to reschedule.	iGEG0710044		209	Y	
4/17/2006	Bradenhead	OK. All Equipment and Location in Good Shape.	iGEG0605344		209		
8/22/2005	Pressure Test	OK. All Equipment and Location in Good Shape.	iGEG0517439		209		
4/6/2004	Bradenhead	Normal Routine Activity A-OK. All Equipment and Location in Good Shape.	iMLB04090294		211		
6/2/2003	Bradenhead	A-OK. All Equipment and Location in Good Shape.	iGEG0312142		209		
4/2/2002	Bradenhead	A-OK. All Equipment and Location in Good Shape.	iGEG0202829		209		
3/8/2001	Bradenhead	All OK. All Equipment and Location in Good Shape.	iGEG0101941		209		
1/12/2000	Pressure Test		iBER0002557		206		
3/4/1999	MIT Witnessed - Other	A-OK. All Equipment and Location in Good Shape.	iBER0001248		206		
3/5/1998	MIT Witnessed - Other	A-OK. All Equipment and Location in Good Shape.	iUNK0000022		206		
3/6/1997	MIT Witnessed - Other		iGW20030000		206		

*100 Ball
Singer Oil*

Total Inspections Performed: 17

Americo Energy Resources, LLC

**Case 14079
OCD Exhibit No. 5**