Examiner Hearing – February 7, 2008 Docket No. 4-08 Page 3 of 8

•	Humphreys No. 001;	30-025-09815;	N-25-25S-36E
•	Maralo Sholes B No. 002;	30-025-09806;	P-25-25S-36E
•	Mcmillan No. 001;	30-025-05511;	N-29-18S-37E
•	Parke Federal No. 001;	30-015-20597;	O-10-17S-30E
•	Parke Federal No. 003;	30-015-20612;	I-10-17S-30E
•	Sholes A No. 003;	30-025-09796;	I-24-25S-36E
•	Sholes B 25 No. 002;	30-025-09808;	B-25-25S-36E
•	Wright Federal Com No. 001;	30-015-21878;	N-29-18S-29E

The Barr H State No. 001 is located approximately 8 miles northeast of Maljamar, in Lea County, New Mexico.

The Bell Ramsay NCT D No. 001 is located approximately 9 miles southwest of Hobbs, in Lea County, New Mexico.

The Eagle No. 001 is located approximately 3 miles west of Jal, in Lea County, New Mexico.

The Humphreys No. 001 is located approximately 4 miles southwest of Jal, in Lea County, New Mexico.

The Maralo Sholes B No. 002 is located approximately 2 miles southwest of Jal, in Lea County, New Mexico.

The Mcmillan No. 001 is located approximately 8 miles west of Hobbs, in Lea County, New Mexico.

The Parke Federal No. 001 and Parke Federal No. 003 are located approximately 4 miles southeast of Loco Hills, in Eddy County, New Mexico.

The Sholes A No. 003 is located approximately 1 mile west of Jal, in Lea County, New Mexico.

The Sholes B 25 No. 002 is located approximately 3 miles Northwest of Jal, in Lea County, New Mexico.

The Wright Federal Com No. 001 is located approximately 8 miles southwest of Loco Hills, in Eddy County, New Mexico.

6. <u>CASE 14078</u>: Application of the New Mexico Oil Conservation Division for a Compliance Order against ERS Resources, LLC. Applicant seeks an Order finding that Operator is in violation of 19.15.4.201 NMAC as to thirty-two wells, requiring Operator to bring the wells to compliance with 19.15.4.201 NMAC by a date certain, and authorizing the Division to forfeit the financial assurance and plug the wells in the event of Operator's non-compliance with the Order. The affected wells are:

•	Artesia Metex Unit No. 005;	30-015-00945;	L-24-18S-27E
•	Artesia Metex Unit No. 006;	30-015-00941;	K-24-18S-27E
•	Artesia Metex Unit No. 008;	30-015-00944;	I-24-18S-28E
•	Artesia Metex Unit No. 011;	30-015-01940;	3-19-18S-28E
•	Artesia Metex Unit No. 012;	30-015-01964;	K-19-18S-28E
•	Artesia Metex Unit No. 013;	30-015-01951;	J-19-18S-28E
•	Artesia Metex Unit No. 014;	30-015-01947;	J-19-18S-28E
•	Artesia Metex Unit No. 016;	30-015-00942;	M-24-18S-27E
•	Artesia Metex Unit No. 020;	30-015-01196;	P-24-18S-27E
•	Artesia Metex Unit No. 021;	30-015-01942;	4-19-18S-28E
•	Artesia Metex Unit No. 022;	30-015-01965;	N-19-18S-28E
•	Artesia Metex Unit No. 023;	30-015-01941;	N-19-18S-28E
•	Artesia Metex Unit No. 024;	30-015-01949;	O-19-18S-28E
•	Artesia Metex Unit No. 026;	30-015-00962;	A-26-18S-27E
•	Artesia Metex Unit No. 027;	30-015-00951;	D-25-18S-27E
•	Artesia Metex Unit No. 029;	30-015-01194;	B-25-18S-27E
•	Artesia Metex Unit No. 031;	30-015-02139;	1-30-18S-28E

Examiner Hearing – February 7, 2008 Docket No. 4-08 Page 4 of 8

•	Artesia Metex Unit No. 032;	30-015-02140;	C-30-18S-28E
•	Artesia Metex Unit No. 035;	30-015-00963;	H-26-18S-27E
•	Artesia Metex Unit No. 036;	30-015-00952;	E-25-18S-27E
•	Artesia Metex Unit No. 039;	30-015-00948;	G-25-18S-27E
•	Artesia Metex Unit No. 040;	30-015-00954;	H-25-18S-27E
•	Artesia Metex Unit No. 041;	30-015-02136;	2-30-18S-28E
•	Artesia Metex Unit No. 042;	30-015-02138;	F-30-18S-28E
•	Artesia Metex Unit No. 044;	30-015-01190;	I-26-18S-27E
•	Artesia Metex Unit No. 045;	30-015-00959;	L-25-18S-27E
•	Artesia Metex Unit No. 049;	30-015-02141;	K-30-18S-28E
•	Artesia Metex Unit No. 051;	30-015-00966;	P-26-18S-27E
•	Artesia Metex Unit No. 052;	30-015-00960;	M-25-18S-27E
•	Artesia Metex Unit No. 054;	30-015-00956;	O-25-18S-27E
•	Artesia Metex Unit No. 056;	30-015-00987;	A-35-18S-27E
•	Artesia Metex Unit No. 058;	30-015-00991;	C-36-18S-27E

The Artesia Metex Unit No. 027, Artesia Metex Unit No. 036, and Artesia Metex Unit No. 058, are located approximately 8 miles southeast of Artesia, in Eddy County, New Mexico.

The Artesia Metex Unit No. 005 and Artesia Metex Unit No. 006 are located approximately 9 miles southeast of Artesia, in Eddy County, New Mexico.

The Artesia Metex Unit No. 016, Artesia Metex Unit No. 026, Artesia Metex Unit No. 029, Artesia Metex Unit No. 035, Artesia Metex Unit No. 045, Artesia Metex Unit No. 052, and Artesia Metex Unit No. 056, are located approximately 10 miles southeast of Artesia, in Eddy County, New Mexico.

The Artesia Metex Unit No. 040 is located approximately 11 miles southeast of Artesia, in Eddy County, New Mexico.

The Artesia Metex Unit No. 020, Artesia Metex Unit No. 032, Artesia Metex Unit No. 039, Artesia Metex Unit No. 042, Artesia Metex Unit No. 051, and Artesia Metex Unit No. 054, are located approximately 12 miles southeast of Artesia, in Eddy County, New Mexico.

The Artesia Metex Unit No. 011, Artesia Metex Unit No. 012, Artesia Metex Unit No. 013, Artesia Metex Unit No. 014, Artesia Metex Unit No. 021, Artesia Metex Unit No. 031, and Artesia Metex Unit No. 041, are located approximately 13 miles southeast of Artesia, in Eddy County, New Mexico.

The Artesia Metex Unit No. 022, Artesia Metex Unit No. 023, and Artesia Metex Unit No. 049, are located approximately 14 miles southeast of Artesia, in Eddy County, New Mexico.

The Artesia Metex Unit No. 008 and Artesia Metex Unit No. 024 are located approximately 16 miles southeast of Artesia, in Eddy County, New Mexico.

- 7. <u>CASE 14079</u>: Application of the New Mexico Oil Conservation Division for a Compliance Order against Americo Energy Resources, LLC. Applicant seeks an order finding operator in violation of 19.15.3.116 NMAC as to two wells; requiring operator to bring the wells into compliance with 19.15.3.116 by a date certain; and assessing penalties. The affected wells are:
 - East Shugart Unit No. 015; API No. 30-015-05687; F-34-18S-31E
 - East Shugart Unit No. 042; API No. 30-015-27670; A-34-18S-31E

The East Shugart Unit No. 015 well is located approximately 9 miles southwest of Maljamar, in Eddy County, New Mexico.

The East Shugart Unit No. 042 well is located approximately 7 miles southwest of Maljamar, in Eddy County, New Mexico.