

L & R WELL SERVICE, INC.

**POST OFFICE BOX 1457
ARTESIA, NEW MEXICO 88211-1457
(505) 748-3835**

WORK TICKET

13268

well file

DATE 1/14/02

COMPANY Jake Cleo Thompson
LEASE Tract 16 well

ORDER OR
CONTRACT NO. Amador Pando

WELL NO. # 13

[illegible]

	$\frac{5}{8}$ "	$\frac{3}{4}$ "	$\frac{7}{8}$ "	1"
RODS				
SUBS				
	$2\frac{3}{8}$ "		$2\frac{7}{8}$ "	
TUBING				

HELPER Humaro Chacon HRS. 9 1/2
HELPER Pablo Bahena HRS. {
HELPER Ed Jones HRS. {
OPERATOR Jesús Valdez HRS. {

士

[Handwritten signature]

L & R WELL SERVICE, INC.

POST OFFICE BOX 1457
ARTESIA, NEW MEXICO 88211-1457
(505) 748-3835

WORK TICKET

13551

DATE 11/15/02

COMPANY Jake Cleo Thompson
LEASE Tract 9

ORDER OR CONTRACT NO. Amador Pando
WELL NO. # 13

WELL DESCRIPTION	HRS.	RATE	TOTAL
Drove crew to location, R.I. H. w/ 9-2 1/2" jts Tagged up on Yunk Iron @ 2762'. R. up power Swivel & Mill Down to 2777'. Circulate hole Clean, laid down Swivel P.O.H. w/ 7 jts, Shut Down.			
Double Derrick w/ 4 men	10.5	145.00	1522.50
7:00 am - 5:30 pm			

	5/8"	3/4"	7/8"	1"
RODS				
SUBS				
TUBING	2 3/8"		2 7/8"	

#1

HELPER Gumaro Chacon HRS. 10 1/2
HELPER Paulo Battena HRS. {
HELPER Ed Jones HRS. {
OPERATOR Jesus Valdez HRS. {

Ref # 2

L & R WELL SERVICE, INC.

POST OFFICE BOX 1457
ARTESIA, NEW MEXICO 88211-1457
(505) 748-3835

WORK TICKET

13552

DATE 1/16/02

COMPANY Gabe Cleo Thompson
LEASE Tract 9

ORDER OR CONTRACT NO. Amador Pando
WELL NO. #13

WELL DESCRIPTION	HRS.	RATE	TOTAL
Drave Crew to location, R.I.H. w/ 7 1/2' Tagged @ 2777' Mill on junk, Metal Down to 2784' Circulate clean. P.O.H. w/ Ybg & Drill Collars plus Mill. Shut well in, shut down for the Day.			
Double Derrick w/ 3 men	10	145.00	1450.00
Pipe Wiper	1	20.00	20.00
3 1/2' Slips	1	80.00	80.00
7:00 am - 5:00 pm			

	5/8"	3/4"	7/8"	1"
RODS				
SUBS				
TUBING	2 3/8"	2 1/8"		

HELPER Gumaro Chacon HRS. 10
HELPER Paulo Bohena HRS. 5
HELPER Ed Jones HRS. 5
OPERATOR Jesus Valdez HRS. 5

1

Paulo 2.

L & R WELL SERVICE, INC.

POST OFFICE BOX 1457
ARTESIA, NEW MEXICO 88211-1457
(505) 748-3835

WORK TICKET

13553

DATE 1/17/02

COMPANY G. C. Thompson
LEASE Tract 9

ORDER OR CONTRACT NO. Amador Pando
WELL NO. #13

WELL DESCRIPTION	HRS.	RATE	TOTAL
Drove Crew to location, R.I.H. w/ 4 1/2" Shoe 2 jts of 4 1/2" Wash Pipe, 8-3 1/2" Drill Collars & 83 jts of 2 7/8" Tbg. R. up Swivel wash over from 2784' to 2844' Circulate Clean. P.O.H. w/ shoe, Run back in w/ 4 1/16 Over Shot, 8-Drill Collars & 81-jts. Got on 2 3/8" Tbg w/ Over Shot, Tried to work Tbg Lapse, Couldnt get Tbg to come loose, Release Over Shot. P.O.H. w/ tools & Shut Down.			
Double Derrick w/ 4 men	10 1/2	145.00	1522.50
3 1/2 Slips	1	80.00	80.00

	5/8"	3/4"	7/8"	1"
RODS				
SUBS				
TUBING	2 3/8"		2 7/8"	

HELPER Lumero Chacon HRS. 10 1/2
HELPER Paulo Bahena HRS. 1
HELPER Ed gones HRS. 1
OPERATOR Jesus Valdez HRS. 1

11/17/02

**POST OFFICE BOX 1457
ARTESIA, NEW MEXICO 88211-1457
(505) 748-3835**

13554

COMPANY J. Cleo Thompson
LEASE Tract 9 will

ORDER OR
CONTRACT NO. Amador Pardo

WELL NO. #13

	$\frac{5}{8}$ "	$\frac{3}{4}$ "	$\frac{7}{8}$ "	1"
RODS				
SUBS				
TUBING	$2\frac{3}{8}$ "		$2\frac{7}{8}$ "	

HELPER Gumaro Chacon HRS. 10
HELPER Paulo Bahena HRS. 7
HELPER Ed Jones HRS. 7
OPERATOR Jesus Valdez HRS. 7



L & R WELL SERVICE, INC.

POST OFFICE BOX 1457
ARTESIA, NEW MEXICO 88211-1457
(505) 748-3835

WORK TICKET

13555

DATE 11/21/02

COMPANY J. Cleo Thompson
LEASE Tract 9

ORDER OR CONTRACT NO. Amador Pando
WELL NO. #13

WELL DESCRIPTION	HRS.	RATE	TOTAL
Drone crew to location. Ran in hole with 6'1/8 shoe, 2 jts. of 4'1/2" wash pipe and 8-3'1/2 drill collars 89 jts. of 2'7/8 tlg. Washed over and clean from 2990' to 3060'. Circulate clean. Pulled out of the hole with shoe run back in with 4'1/16 overshot 3'1/2 jars and 8-3'1/2 drill collar plus 89 jts. of 2'7/8. Fished 2'3/8 tlg at 3060' jar on tlg for 3 hrs. Couldn't free up tlg. Release overshot. Pulled out of the hole with tools. Shut well in. Shut down.			
Double Derrick w 4 men	9 1/2	145.00	1377.50
3 1/2 slips add day	1	20.00	20.00
7:00am to 4:30pm			

	5/8"	3/4"	7/8"	1"
RODS				
SUBS				
TUBING	2 3/8"		2 7/8"	

HELPER Dumaro Chacon HRS. 9 1/2
HELPER Paulo Bahena HRS. 7
HELPER Ed Jones HRS. 7
OPERATOR Jesus Valdez HRS. 7

[Signature]

L & R WELL SERVICE, INC.

POST OFFICE BOX 1457
ARTESIA, NEW MEXICO 88211-1457
(505) 748-3835

WORK TICKET

13556

DATE 1/22/02

COMPANY

J. Cleo Thompson
Tract 9

ORDER OR
CONTRACT NO.

Amador Pando

LEASE

WELL NO.

#13

WELL DESCRIPTION

HRS.

RATE

TOTAL

Drone to location. Run in with 6' 1/8 shoe,
3 jts. of w. pipe and 90 jts. of 2 7/8"
they wash over from 3060' to 3092'.
Circulate clean. Pulled out of hole with
shoe. Run back in with 4" 11/16 overshot
3 1/2 jars and 8 - 3 1/2 drill collars plus
90 jts. of 2 7/8. Fish 2 3/8 they at 3040'
jar on the string for an hour the
2 3/8 parted. Pulled out of hole with fish
pull below the fish with 49' of the 2 3/8
they shut well in. Shut down.

Double Derrick w 4 men
3 1/2 slips add day

10

145.00

1450.00

1

20.00

20.00

7:00 am to 5:00 pm

	5/8"	3/4"	7/8"	1"
RODS				
SUBS				
	2 3/8"	2 7/8"		
LOGGING				

HELPER

Sumario Chacon

HRS. 10

HELPER

Paulo Bahena

HRS. 7

HELPER

Nicolas Salcido

HRS. 7

OPERATOR

Jesus Valdez

HRS. 7

APR 12

**POST OFFICE BOX 1457
ARTESIA, NEW MEXICO 88211-1457
(505) 748-3835**

13557

COMPANY J Cleo Thompson
LEASE Tract 9

WELL NO. # 13

7:00 am - 5:30 pm

	$\frac{5}{8}$ "	$\frac{3}{4}$ "	$\frac{7}{8}$ "	1"
RODS				
SUBS				
	$2\frac{3}{8}$ "		$2\frac{7}{8}$ "	
TUBING				

HELPER Gumaro Chacon HRS. 10 1/2
HELPER Paulo Bahena HRS. 10 1/2
HELPER Ed Jones HRS. 10 1/2
OPERATOR Jesus Valdez HRS. 10 1/2

21

RR2

L & R WELL SERVICE, INC.

POST OFFICE BOX 1457
ARTESIA, NEW MEXICO 88211-1457
(505) 748-3835

WORK TICKET

13558

DATE 1/24/02

COMPANY J. Cleo Thompson
LEASE Tract 9

ORDER OR CONTRACT NO. Amador Pando
WELL NO. #13

WELL DESCRIPTION

Drove to location. Ran in hole with 20 jts. Tagged at same place at 3125'. Pulled out of the hole with shoe. Ran in hole with 4" 116 overshot and 3 1/2 jars, 8 drill collars plus 91 jts. of 2 7/8. Fished 2 3/8 thg at 3060'. Pulled out of the hole with fish and had 2 jts. of 2 3/8 SN. 4' perforated sub. SN, and 15' MA. Run back in with 6 1/8" drill bit, 8-3 1/2 drill collars and 94-2 7/8 thg. Clean from 3125' to TD at 3150'. Circulate clean and pull and lay down 60 jts. Delivered to Thompson's yard. Shut down.

Double Derrick w 4 men 10 1/2 145.00 1522.50

7:00am - 5:30pm

	5/8"	3/4"	7/8"	1"
RODS				
SUBS				
	2 3/8"		2 7/8"	
TUBING				

HELPER Dumaro Chacon HRS. 10 1/2
HELPER Pablo Bahena HRS. 7
HELPER Ed Jones HRS. 7
OPERATOR Jesus Valdez HRS. 7

APR 2.

**POST OFFICE BOX 1457
ARTESIA, NEW MEXICO 88211-1457
(505) 748-3835**

13559

COMPANY J. Cleo Thompson ORDER OR CONTRACT NO. Amador Pando
LEASE Tract 9 WELL NO. # 13

6:00am to 2:00 pm

	5/8"	3/4"	7/8"	1"
RODS				
SUBS				
	2 3/8"		2 7/8"	
TUBING				

HELPER Guillermo Chacon HRS. 8
HELPER Paulo Bahena HRS. 7
HELPER Ed Jones HRS. 7
OPERATOR Jesus Valdez HRS. 7

1422

**POST OFFICE BOX 1457
ARTESIA, NEW MEXICO 88211-1457
(505) 748-3835**

13560

DATE 1/28/02

COMPANY.

J Cho Thompson
Tract 9

ORDER OR
CONTRACT NO.

Amador Pando

LEASE

WELL NO.

#13

6:00 am - 1:00 pm

RODS	$\frac{5}{8}$ "	$\frac{3}{4}$ "	$\frac{7}{8}$ "	1"
SUBS				
TUBING	2 $\frac{3}{8}$ "		2 $\frac{7}{8}$ "	

HELPER Dumaro Chacon HRS. 7

HELPER Paulo Bakena HRS. 7

HELPER Ed Jones HRS. 1

OPERATOR Jesus Valdez HRS. 1

RR2

POST OFFICE BOX 1457
ARTESIA, NEW MEXICO 88211-1457
(505) 748-3835

13561

Will file

DATE 1/29/02

COMPANY

J. Cleo Thompson
Tract 9

ORDER OR
CONTRACT NO.

Amador Pando

LEASE

WELL NO. #13

WELL DESCRIPTION	HRS.	RATE	TOTAL
Drove to location. Ran in hole with 4 1/2 x 5 3/4 shoe, 5 centralizers and 65-4 1/2 jts. of casing. Put shoe at 2733'. Rig up Halliburton pump cement down. Close valve and shut down.			
Double Derrickmen ⁴	8 1/2	145.00	1232.50
3 1/2 Slips (add)	1	20.00	20.00
6:00am to 2:30 pm			

	5/8"	3/4"	7/8"	1"
RODS				
SUBS				
	2 3/8"		2 7/8"	
TUBING				

HELPER Dumario Chacon HRS. 8 1/2
HELPER Paulo Bahena HRS. 7
HELPER Ed Jones HRS. 7
OPERATOR Jesus Valdez HRS. 7

AR2

L & R WELL SERVICE, INC.

POST OFFICE BOX 1457
ARTESIA, NEW MEXICO 88211-1457
(505) 748-3835

WORK TICKET

13562

DATE 11/30/02

COMPANY J. Cleo Thompson
LEASE Tract 9

ORDER OR CONTRACT NO. Amador Pardo
WELL NO. # 13

WELL DESCRIPTION	HRS.	RATE	TOTAL
Drive to location. Loaded 95-2 ³ / ₈ jts. from yard. Pick up and run in hole 3 ¹ / ₄ drill bit, 6-3 ¹ / ₈ drill collars and 82-2 ³ / ₈ jts. Tag and drill flow shoe at 2733. Drill for 2 hours. Circulate clean. Shut down for day.			
Double Derrick w ⁴ men	11 ¹ / ₂	145.00	1667.50
3 ¹ / ₂ Slips (add)	1	20.00	20.00
12:00 am - 5:30 pm			

	5/8"	3/4"	7/8"	1"
RODS				
SUBS				
TUBING	2 ³ / ₈ "	2 ⁷ / ₈ "		

HELPER Dumaro Chacon HRS. 11¹/₂
HELPER Paulo Bahena HRS. 7
HELPER Ed Jones HRS. 7
OPERATOR Jesus Valdez HRS. 7

11/30/02

LEASE OPERATOR

L & R WELL SERVICE, INC.

POST OFFICE BOX 1457
ARTESIA, NEW MEXICO 88211-1457
(505) 748-3835

WORK TICKET

13563

DATE 1/31/02

COMPANY J. Cleo Thompson
LEASE Tract 9

ORDER OR CONTRACT NO. Amador Pando
WELL NO. #13

WELL DESCRIPTION	HRS.	RATE	TOTAL
Drive to location. Drill flow shoe at 2733 through down to TD 3150. Pulled out of the hole with tug. Lay down 6 drill collars. Run back in with SN and 98-2 3/8 jts. Rig up swab equipment. Made 7 runs. Pull 17 bbls. Close well in. SN at 3056.			
Double Derrick w/4	12	145.00	1740.00
2" Swab Cups	2	20.25	40.50
Oil Saver Rubbers	2	11.20	22.40
6:00am to 6:00pm			

	5/8"	3/4"	7/8"	1"
RODS				
SUBS				
TUBING	2 3/8"		2 7/8"	

HELPER Mumario Chacon HRS. 12
HELPER Paulo Bahena HRS. 7
HELPER Ed Jones HRS. 7
OPERATOR Jesus Valdez HRS. 7

[Signature]

LEASE OPERATOR

**POST OFFICE BOX 1457
ARTESIA, NEW MEXICO 88211-1457
(505) 748-3835**

13564

DATE 2/1/02

COMPANY J. Clio Thompson
LEASE Tract 9

ORDER OR
CONTRACT NO. Amador Pando

WELL NO. #13[illegible]

	$\frac{5}{8}$ "	$\frac{3}{4}$ "	$\frac{7}{8}$ "	1"
RODS				
SUBS				
	$2\frac{3}{8}$ "	$2\frac{1}{8}$ "		
PIPE				

HELPER Dumaro Chacon HRS. 9 1/2

HELPER Paulo Bahena HRS. 7

HELPER Ed Jones HRS. 7

OPERATOR Jesus Valdez HRS. 7

[Signature]

LEASE OPERATOR

L & R WELL SERVICE, INC.

POST OFFICE BOX 1457
ARTESIA, NEW MEXICO 88211-1457
(505) 748-3835

WORK TICKET

13565

DATE 2/4/02

COMPANY J Cleo Thompson
LEASE Tract 9 Well

ORDER OR CONTRACT NO. Amador Pando
WELL NO. #13

WELL DESCRIPTION	HRS.	RATE	TOTAL
Drove to location. Run in hole with 4 1/2" 32A packer, seating nipple and 86 joints of 2 3/8" Rig up swab. Made 3 swab runs from 1700' down to seating nipple. Set packer @ 2682'. Pump acid. Close well in for 30 minutes. Start swabbing from surface down to seating nipple in 6 swab runs. Release packer. Pull out of hole with tubing and packer. Run in hole with seating nipple and 98 joints of 2 3/8" tubing. Set seating nipple @ 3056'. Hang well on. Rig up swab. Made 21 swab runs. Recovered 37 bbls of water. Close well in. Shut down for day.			
Double Derrick + 4 Men	12 1/2	145.00	1812.50
Pipe Wiper	1	20.00	20.00
2" Swab Cups	4	20.25	81.00
Oil Saver Rubbers	4	11.20	44.80
6:00 am - 6:30 pm			

	5/8"	3/4"	7/8"	1"
RODS				
SUBS				
TUBING	2 3/8"		2 7/8"	
	98			

HELPER Gumaro Chacon HRS. 12 1/2
HELPER Paulo Bahena HRS. 12 1/2
HELPER Ed Jones HRS. 12 1/2
OPERATOR Jesús Valdez HRS. 12 1/2

[Signature]

LEASE OPERATOR

**POST OFFICE BOX 1457
ARTESIA, NEW MEXICO 88211-1457
(505) 748-3835**

13566

DATE 2/5/02

ORDER OR
CONTRACT NO. Amador Pardo

WELL NO. #13

6:00 am - 3:30 pm

 $2 \times 1\frac{1}{2} \times 10$

HELPER Dumano Chacon HRS. 9 1/2

HELPER Paulo Bahena HRS. 7

HELPER Ed Jones HRS. 7

OPERATOR Jesus Valdez HRS. 7

PL 12