

Well_Name: MARSHAL API: 3E+09
 Location: K-19-23.0S-33E 1980 FSL 1910 FWL
 Lat: 32.28846 Long: -103.6135
 Operator: NPRONGHC County: Lea
 Land Type: Federal Well Type: SWD
 Spud Date: Plug Date:
 Elevation GL: Depth TVD 5216 APC Status:

Year: 2007

Pool Name: SWD; DELAWARE

Month	Gas(MCF)	CO2(MCF)	Water(BBL)	Other(BBL)	Days Injected
January	0	0	2	0	0
February	0	0	0	0	0
March	0	0	2	0	0
April	0	0	2	0	0
May	0	0	2	0	0
June	0	0	2	0	0
July	0	0	2	0	0
August	0	0	2	0	0
September	0	0	0	0	0
October	0	0	0	0	0
November	0	0	0	0	0
December	0	0	0	0	0

07-Jan-08

Well Inspection History

API Number: **30-025-08359-00-00**

Well Name & No.: **MARSHALL**

Operator: **PRONGHORN MANAGEMENT CORP,**

District: **HOBBS**

County Name: **LEA**

Field: **MARSHALL**

Legal: **S: 19 T: 23S R: 33E**

Well Type: **SALT WATER DISPOSAL WELL**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
5/18/2006	Compliance Verification	Status Check	iLWH0613847		102		
	NO CHANGE						
3/8/2004	Compliance Verification	Enforcement Action Follow-u	iLWH0406858		102	Y	
	Idle Well (Rule 201), SHUT IN.						
8/22/2003	Routine/Periodic	Normal Routine Activity	iLWH0323454		102	Y	
	IDLE WELL. SHUT IN.						
9/3/2002	Routine/Periodic	Normal Routine Activity	iELG02246487		114		
	A-OK. All Equipment and Location in Good Shape.						
3/8/2002	Routine/Periodic	Normal Routine Activity	iELG02067525		114		
	A-OK. All Equipment and Location in Good Shape. CK FILE WHEN IS WELL DUE (MIT)						
3/14/1995	MIT Witnessed - Other		unk0011779		109		
	REP LEAK 782-813 W/125SX						
9/21/1994	MIT Witnessed - Other		unk0011778		109		
	PRSS-360-40# BUILDUP-COPY FOR JS						

Total Inspections Performed: 7