

Case No. 14326

July 9, 2009

OIL CONSERVATION DIVISION V. NACOGDOCHES OIL & GAS, INC.

SFRR 042: 30-031-20745

01-Jul-09

Well Inspection History

API Number: **30-031-20745-00-00** Well Name & No.: **SANTA FE RAILROAD**
 Operator: **NACOGDOCHES OIL AND GAS, INC, NACO** District: **AZTEC** County Name: **MCKINLEY**
 Field: **SANTA FE RAILROAD** Legal: **S: 7 T: 17N R: 8W**
 Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmtyRqDt	Insp. By	Viol. SNC	Failed Codes
5/14/2008	Routine/Periodic	Normal Routine Activity	IMPK0913141		312		
		No Pumping Unit. Well shut in. No fluid in it.					
5/14/2008	Routine/Periodic	Normal Routine Activity	IMPK0907229		312		
		Equipment and location in good shape.					
9/15/2008	Routine/Periodic	Normal Routine Activity	IMPK0825942		312		
		no motor on Pumping Unit. Line running - hose ran from tubing towards tank battery					
5/14/2008	Routine/Periodic	Normal Routine Activity	ILJC08135474		319		
		No Motor on Pumping Unit. All other equipment ok.					
4/28/2004	Routine/Periodic	Normal Routine Activity	IDGF0412154		304		
		Location needs attention. Equipment OK.					
4/28/2003	Routine/Periodic	Normal Routine Activity	IWBVM0311855		308		
		A-OK. All Equipment and Location in Good Shape.					
11/2/2000	Routine/Periodic	Normal Routine Activity	IWBVM0020857		308		
		OK. All Equipment and Location in Good Shape.					

Total Inspections Performed: 7

SFRR 042: 30-031-20745

- Inspection May 11, 2009

NACOGDOCHES OIL AND GAS, INC.
EMERGENCY NUMBER (936) 560-4747
HUGHAN FIELD
MCKINLEY COUNTY, NEW MEXICO
SANTA FE RAILROAD # 042
2310' FNL & 1650' FWL
ULSTR E-7-17N-8W
API # 30-031-20745
GPS COORDINATES: N 35.71872 W -107.72867
MAP DATUM: NAD 27 CONUS

SFRR 042: 30-031-20745

- Inspection May 11, 2009



SFRR 004: 30-031-05151

01-Jul-09

Well Inspection History


API Number: **30-031-05151-00-00** Well Name & No: **SANTA FE RAILROAD**
 Operator: **NACOGDOCHES OIL AND GAS, INC, NACO** District: **AZTEC** County Name: **MCKINLEY**
 Field: **SANTA FE RAILROAD** Legal: **S: 7 T: 17N R: 8W**
 Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmbyRqDt	Insp. By	Viol. SNC	Failed Codes
5/11/2009	Routine/Periodic	Normal Routine Activity	IMPK0913145				
5/12/2009	Routine/Periodic	Normal Routine Activity	IMPK0907229				
9/15/2008	Routine/Periodic	Normal Routine Activity	IMPK0825948		312		
5/14/2008	Routine/Periodic	Normal Routine Activity	IIJC08135488		319		
7/2/2007	Routine/Periodic	Normal Routine Activity	IMPK0718425		312		

Total Inspections Performed: 5

SFRR 004: 30-031-05151

● Inspection May 11, 2009



SFRR 004: 30-031-05151

● Inspection May 11, 2009



SHU 54: 30-031-20407

01-Jul-09

Well Inspection History

API Number: **30-031-20407-00-00** Well Name & No: **SOUTH HOSPACH UNIT**
 Operator: **NACOGDOCHES OIL AND GAS, INC, NACO** District: **AZTEC** County Name: **MCKINLEY**
 Field: **SOUTH HOSPACH UNIT** Legal: **S: 12 T: 17N R: 9W**
 Well Type: **INJECTION - (ALL TYPES)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmduRqDt	Insp. By	Viol. SNC	Failed Codes
4/13/2010	Routine/Periodic	Normal Routine Activity	IMPK0913532		312		
4/13/2010	Routine/Periodic	Normal Routine Activity	IMPK0913349		312		
9/5/2008	Routine/Periodic	Normal Routine Activity	ISGC0825242		318		
5/14/2008	Routine/Periodic	Normal Routine Activity	IJC08105489		319		
11/13/2007	Routine/Periodic	Normal Routine Activity	IMPK0731826		312		
12/7/2006	Routine/Periodic	Normal Routine Activity	IMPK0634225		312		
9/27/2006	MIT Witnessed - Other	Normal Routine Activity	IMPK0627050		312		
7/21/2004	Routine/Periodic	Normal Routine Activity	IDGF0423357		304		
12/4/2003	Routine/Periodic	Normal Routine Activity	IWBV0333356		308		
9/15/2000	Routine/Periodic	Normal Routine Activity	IWBV0025937		308		

Total Inspections Performed: 10


SHU 54: 30-031-20407

● Inspection May 13, 2009



SHU 54: 30-031-20407

● Inspection May 13, 2009




SHU 54: 30-03I-20407

- Inspection May 13, 2009



SHU 54: 30-03I-20407

- Follow-up Inspection May 15, 2009



HSU 93: 30-031-206II

08-Jul-09

Well Inspection History

API Number: 30-031-20611-00-00

Well Name & No.: **HOSPAH SAND UNIT**

Operator: **NACOGDOCHES OIL AND GAS, INC, NACO**

District: **AZTEC**

County Name: MCKINLEY

Field: **HOSPAH SAND UNIT**


Legal: S: 1 T: 17N R: 9W

Well Type: **INJECTION - (ALL TYPES)**

Insp. Ct	Insp Type	Insp Purpose	Insp No.	RmlyRqCt	Insp By	Viol. SNC	Failed Codes
7/6/2009	Routine/Periodic well disconnected - pictures well disconnected	Normal Routine Activity	IMPK0918373		312		
7/11/2009	Routine/Periodic well disconnected	Normal Routine Activity	IMPK0918373		312		
5/15/2009	Routine/Periodic well disconnected	Normal Routine Activity	IMPK0913532		312		
5/13/2009	Routine/Periodic well still disconnected pictures no well sign	Normal Routine Activity	IMPK0913333		312		
5/05/2009	Routine/Periodic 0 on both gauges - bull plug in place	Normal Routine Activity	IMPK0912756		312		
04/06/2009	Routine/Periodic	Normal Routine Activity	IMPK0912125		312		
Well removed again with SCD on gauge - equipment checked & replaced as needed. Terry requested this morning (May 19) that the well be put back on production so he could get the shut-in pressure. He also requested an initial sample from the well which was taken after dark.							
5/11/2009	Routine/Periodic	Normal Routine Activity	IMPK0912125		312		
this well shows fluid column activity at least in 2000' found during testing. AHS SCD on gauge. Terry thought sand had been added to seal area. This well has stopped being tested by SCD logs.							
5/14/2008	Routine/Periodic No Well Sign (Rule 102). Equipment in good shape.	Normal Routine Activity	IJC08135397		319		

HSU 93: 30-03I-206II

● Inspection April 30, 2009



HSU 93: 30-03I-206II

● Inspection April 30, 2009

