

11-Aug-09

Well Inspection History

API Number: **30-025-27984-00-00**

Well Name & No.: **POST**

Operator: **PLATINUM EXPLORATION INC, CONRAD T**

District: **HOBBS**

County Name: **LEA**

Field: **POST**

Legal: **S: 1 T: 14S R: 37E**

Well Type: **SALT WATER DISPOSAL WELL**

Case 14380

OCD Exhibit 8

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
7/27/2009	Compliance Verification	Status Check	iMGB0920860		119	Y	100 113
No Well Sign (Rule 19.15.16.8). NEED TO INSTALL WELL SIGN AT WELL. CORRECT SIGN AT TANK BATTERY TO REFLECT CURRENT OPERATOR. FLOWLINE LEAK INSIDE OF DIKED AREA AT TANK BATTERY IS STILL LEAKING. MAKE REPAIRS ASAP! RULE 19.15.29.11. TANKS CHIMES, LOADLINE VALVES STILL SHOW SIGNS OF LEAKAGE AND LOADLINE CONTAINMENTS NEED TO BE EMPTIED. THIS IS 2ND LETTER OF NON-COMPLIANCE.							
6/24/2009	Routine/Periodic	Normal Routine Activity	iMGB0917557		119	Y	100 8
NO Well Sign (Rule 119.15.16.8). NEED TO INSTALL WELL SIGN AT WELL, ALSO NEED CURRENT OPERATOR ON SIGN AT TANK BATTERY. ALSO REPAIR FLOWLINE LEAK AT TANK BATTERY, REMOVE CONTAMINATED SOIL, ASAP! NEED TO REMOVE CONTAMINATED SOIL STOCKPILED WEST OF TANK BATTERY, REPAIR OR REPLACE LEAKING VALVES ON TANKS, ALSO ADDRESS LEAKS AROUND TANK CHIMES, (RULE 19.15.29.11) THIS IS 1ST LETTER.							
6/5/2009	Pressure Test	Normal Routine Activity	iSAD09156549		118		
FAILED PT;							
6/3/2009	Bradenhead	Normal Routine Activity	iSAD09154482		118	Y	
Well IS TA'D WAS DUE UP FOR PRESSURE TEST BUT TRUCK COULD NOT COME INTO FIELD; PRESSURE TEST HAS NOT BEEN WITNESSED; LAST PRESSURE APRVD FOR TA STATUS IN 2002;							
4/20/2007	Bradenhead		iSAD07004405		118	Y	
CELLAR HAS ABOUT 6" OF FLUID; COMB. OF OIL & WATER; USED VAC. TRK DAY BEFORE TO EMPTY; POSSIBLY LEAKING UNDERGROUND AND RISING TO SURFACE; TURN OVER TO ENVIRONMENTAL DEPT. ****FOR RECORD ONLY WRONG WELL S/BE POST #2****							
5/4/2005	File and Compliance Review	Status Check	iSAD05124344		118		
S/RPT OF TA STATUS, CHART RUN 3/17/2005, APRVD BY GARY WINK 3/30/05: TA EXPIRES 3/17/2010;(SAD)							
4/5/2005	File and Compliance Review	Normal Routine Activity	iBEP05095382		111		
Review wellfile for C103 SRO. Terms of the Lindenmuth ACO have been met. Cleared all of my compliance on this well.							
3/18/2005	Routine/Periodic	Normal Routine Activity	iELG05077495		114	Y	
No Well Sign (Rule 103). NEED TO INSTALL A WELL SIGN. THIS IS THE 2ND LETTER OF NON-COMPLIANCE.							
3/17/2005	Pressure Test	Normal Routine Activity	iBEP05076615		111		
Witness TA pressure test. Well passed OK							
1/27/2005	File and Compliance Review	Normal Routine Activity	iSP050272963		117		
WELL IS UNDER ACO DATED 12/13/04. WELL MUST BE IN COMPLIANCE BY 03/31/05.							
12/16/2004	Bradenhead		iSAD04314305		114	Y	
Idle Well (Rule 201) THIS WELL HAS BEEN IDLE A LONGTIME-- NO INJ. LINE-- NEED TO T/A , P/A OR PUT WELL ON INJ. ALSO, WELL NEEDS A WELL SIGN. NEED TO RESPOND ASAP-- THE 3RD LETTER OF NON-COMPLIANCE WAS (9-19-02).							
8/26/2004	Pre-Operation (MIT Schedule	Normal Routine Activity	iBEP04239328		111		
Review wellfile and compliance correspondence. Write PP and gather documentation for hearing							
9/26/2003	Pressure Test	Normal Routine Activity	iBEP03269251		111		
TA tst. Well took 54bbbls to load. Would not hold prs..							
9/11/2003	Routine/Periodic	Normal Routine Activity	iBEP03254552		111		
No show for scheduled tst. Sylvia called and informed me that Lindemuth rescheduled for 25th of this month..							
10/24/2002	Routine/Periodic	Normal Routine Activity	iSAD02297488		113		
GORDON DEAN CALLED 10/24/02 AND SPOKE TO BILLY PRICHARD; HE SAID HE DID HAVE A CIBP ABOVE PERFS. BILLY INFORMED HIM MIT WOULD BE ADEQUATE IF IT WOULD PASS. RONNIE RODGERS IS TO CALL BILLY WHEN MIT IS READY. (SAD)							
10/9/2002	Pressure Test		iSAD02254377		111	Y	
Well failed due to no tst. No show, Well has been idle for extended period of time. Several letters written, Start RBDMS compliance tracking...							
9/19/2002	Routine/Periodic	Normal Routine Activity	iBEP02262456		111	Y	
This well has been SI for extended period of time, no well sign TA or PA or repair and return to production, 3RD LETTER OF NON-COMPLIANCE. ***OPERATOR CONTACT OCD DISTRICT OFFICE REGARDING FUTURE INTENTIONS FOR WELL OR WILL BE SENT FOR HEARING*** 30 DAYS.							
1/8/2002	Routine/Periodic	Normal Routine Activity	iBEP02008357		111		
Well is still idle....							
10/4/2001	Routine/Periodic	Normal Routine Activity	iBEP01277471	1/7/2002	111	Y	
Well is idle, No disposal line, No well sign							
6/5/2001	Routine/Periodic	Normal Routine Activity	iBEP01156488		111	Y	
This well has been idle for extended period of time, Non compliance of Order R9210, Letter sent previously							

Total Inspections Performed: 21