[redacted]



INTERIOR—GEOLOGICAL SURVEY, RESTON, VIRGINIA—1973

OGRAPHIC LAND SURVEYORS
908 WEST WALL
MIDLAND, TEXAS 79701
682-1653

QUADRANGLE LOCATION

ROAD CLASSIFICATION

Primary highway, hard surface

Light-duty road, hard or improved surface

Secondary highway, hard surface

Unimproved road

Interstate Route U. S Route State Route

[redacted]

N3207.5—W10330/7.5

1973

AMS 5248 II NE—SERIES V881