


R 10 W

T 29 N



Cross Timbers Oil Company

SAN JUAN COUNTY, NEW MEXICO

TRUJILLO GAS COM #1-R

ISOPACH MAP

PICTURED CLIFFS SANDSTONE

ESTIMATED FT. OF PERMEABILITY FROM
SP LOG CUTOFFS

Contour Interval: 10 feet

Geologist: Randy Hosey

June 2000

TRJ_1RSS.GPF

EXHIBIT

5

1000. 0. 1000. 2000. 3000. 4000. 5000. feet



= Pictured Cliffs Production

= Est. feet of Permeability based on
SP response

50'