

Schlumberger

REPEAT FORMATION TESTER

COUNTY GRADUO
FIELD GRADUO
LOCATION LLANO 34 STATE COM #1
WELL LLANO 34 STATE COM #1
COMPANY MINERALS INC.

COMPANY MINERALS INCORPORATED

LLANO 34 STATE COM #1
BOX 1320
LEA, NEW MEXICO 88240

WELL LLANO 34 STATE COM #1

FIELD GRADUO RIDGE MORROW EAST

COUNTY LEA STATE NEW MEXICO

LOCATION 1650' FSL & 660' FEL

Other Services:
CL
C/L/FDC
D.L.
BHT

API SERIAL NO. SEC 34 TWP 21-S RANGE 34-E

Permanent Datum: G.L. Elev.: 3651
Log Measured From K.B. 21 Ft. Above Perm. Datum
Drilling Measured From K.B.

Elev.: K.B. 3652
D.F. 3651
G.L. 3651

Date	9-1-79
Run No.	ONE
Test No's.	
Type Fluid in Hole	SALT MUD
Dens.	12.2
Visc.	55
pH	8.5
Fluid Loss	2
Source of Sample	CIRC
Rm @ Meas. Temp.	.05 @ 99 °F
Rmf @ Meas. Temp.	.04 @ 99 °F
Rmc @ Meas. Temp.	.08 @ 99 °F
Source: Rmf Rmc	M C
Rm @ BHT	.03 @ 177 °F
Circulation Stopped	1800 8-31
Logger on Bottom	0000 9-2
Max. Rec. Temp.	177 °F
Recorded By	MILLNER
Witnessed By	COLLINS

Run No.	Bit	From

BEFORE THE OIL CONSERVATION COMMISSION
Santa Fe, New Mexico
Case No. 12622 Exhibit No. 18
Submitted by:
NEARBURG EXPLORATION COMPANY, L.L.C.
Special Commission Hearing: September 10, 2002

ORD	To

The well name, location and borehole reference data were furnished by the customer.

EQUIPMENT DATA			
Run No.	ONE	Run No.	ONE
RFP No.	8042	RFP No.	8042
RPP No.	1571	RPP No.	1571
Operating rig time		Operating rig time	
Logging Truck No.		Logging Truck No.	
F.T. Truck No.		F.T. Truck No.	